



**VOLKSWAGEN Transporter: 1CJZ037**

Vinnumber:	<b>WV1ZZZ7HZCH054406</b>	Versionname:	<b>TRANSP.1200 B/F SWB 84PK</b>
First Registrationdate:	<b>15/12/2011</b>	Fiscalpower:	
Expertise Mileage:	<b>126146</b>	Power Kw:	<b>62</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>1426</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/65/16/106 T Steel</b>			
Winter tyres:	Fr.L. <b>Michelin: 4 mm</b>	Fr.R. <b>Michelin: 4 mm</b>	
	Re.L. <b>Michelin: 4 mm</b>	Re.R. <b>Michelin: 4 mm</b>	

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT 783,96

Bumper R, Not original part, E - Replace 329,40



Wheel cover RL, Missing, E - Replace 0,00



Wheel cover FL, Missing, E - Replace 0,00



Ignition key, Missing, E - Replace 150,00



Boot lid covering R, Broken, E - Replace 189,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Wheel cover FR, Missing, E - Replace 0,00



Outside rear-view mirror housing L, Bad repair, LI - Repair and paint (complete) 115,56



Wheel cover RR, Missing, E - Replace 0,00

