



SKODA SUPERB COMBI: XW5453

Vinnumber:	TMBLE9NP7H7528761	Versionname:	2.0 TSI 206KW DSG6 4WD L&K
First Registrationdate:	27/02/2017	Fiscalpower:	
Expertise Mileage:	133405	Power Kw:	206
Bodytype:		Body color:	Black
Gearbox:	Automatic	Rims summer:	Aluminium
Transmission:	Front	Oil level:	OK
Fueltype:	Petrol	Parking lot:	3114
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Seats R heated
Windows electric R	Seats F L ventilated
Cruise Control	Seats F R ventilated
Steering wheel multifunctional	Sun Roof electric
Seats F heated	Panoramic roof
Radio multimedia	Central consol F
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control
	Luggage cover
	Front parking sensors
	Rear parking sensors
	Type of Tow bar
	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/40/19/92 Y LightMetal			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT

1900,72

Alloy rim FR, Scratch(es), LI - Repair and paint (complete)

114,00



Alloy rim RL, Scratch(es), LI - Repair and paint (complete) 114,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 304,99



Wing RR, Scratch(es), It - Spot repair 127,12



Engine protection plate, Deformed / Strained, E - Replace 64,50



Door FR, Dent(s), PDR - Paintless dent repair 69,30



Alloy rim FL, Scratch(es), LI - Repair and paint (complete) 114,00



Alloy rim RR, Scratch(es), LI - Repair and paint (complete) 114,00



Door FL, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 304,99



Door RR, Scratch(es), LI - Repair and paint (complete) 458,42



Wing trim RL, Dent(s), E - Replace 115,40

No pictures to display