



<b>BMW X1: ZK6046</b>			
Vinnumber:	<b>WBAJH710603G12576</b>	Versionname:	<b>xDrive18dA (110 kW)</b>
First Registrationdate:	<b>12/02/2019</b>	Fiscalpower:	
Expertise Mileage:	<b>50854</b>	Power Kw:	<b>110</b>
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>2509</b>
Fueltype:	<b>Diesel</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

<b>Options</b>			
Number of keys total:	<b>1</b>	Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	<b>No Tow bar</b>
Type of headlighting:	<b>Headlighting Halogen</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining artificial leather</b>		
Type of climate control:	<b>Manual climate control</b>		

**Limited Technical Inspection**

**Degree of wear**

<b>225/55/17/97 H</b>				
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>
Tyre profile depth FL:				<b>4</b>
Tyre profile depth FR:				<b>4</b>
Tyre profile depth RL:				<b>4</b>
Tyre profile depth RR:				<b>4</b>
Tyre size FL:				<b>225/55 R 17 97 H</b>
Tyre type FL:				<b>Winter</b>
Tyre make FL:				<b>261</b>
Tyre make RL:				<b>261</b>

<b>Assistance equipment</b>			
Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

<b>Total cost ex VAT</b>	<b>1580,84</b>
<b>Tailgate / Boot, Scratch(es), Acceptable</b>	<b>0,00</b>



<b>Bumper trim R, Dent(s) and scratch(es), Smart repair</b>	<b>121,70</b>
---	---------------



Wing RL, Dent(s), Paintless dent repair

69,30



Ignition key, Missing, Replace

300,00

*No pictures to display*

Fog lamp L, Crack, Replace

166,00



Backrest cover FR, Scratch(es), Smart repair

70,75



Boot cover, Missing, Replace

60,00



Rear window, Scratch(es), Replace

445,00



Bonnet, Chemical polution, Repair and paint (complete)

348,09



Bumper R, Scratch(es), Acceptable

0,00



Door RR, Scratch(es), Acceptable

0,00

