



BMW X4: UH6284

| | | | |
|------------------------------------|--------------------------|-------------------------|---------------------------|
| Vinnumber: | WBAVJ310X0LG13891 | Versionname: | xDrive25d (170 kW) |
| First Registrationdate: | 14/02/2019 | Fiscalpower: | |
| Expertise Mileage: | 52087 | Power Kw: | 170 |
| Bodytype: | | Body colour: | White |
| Gearbox: | Automatic | Type of rims (mounted): | Aluminium |
| Transmission: | | Parking lot: | 2729 |
| Fueltype: | Diesel | | |
| Maintenance: | OK | | |
| Type of rims (mounted): | Aluminium | | |
| Certificate of Conformity: | Yes | | |
| Category: | Passenger Car | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Number of keys total | 2 | Seats electric F L | |
| Cruise Control | | Seats electric F R | |
| Steering wheel multifunctional | | Luggage cover | |
| Seats F heated | | Front parking sensors | |
| Radio multimedia | | Rear parking sensors | |
| Type of headlighting | Headlighting LED | Type of Tow bar | No Tow bar |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |
| Sport seats | | | |

Limited Technical Inspection

Degree of wear

| | | | | |
|-----------------------|------------------------|----------------------|-------|--------------------------|
| | 245/50/19/92 MS | | | |
| Winter tyres: | Fr.L. | Pirelli: 5 mm | Fr.R. | Pirelli: 5 mm |
| | Re.L. | Pirelli: 5 mm | Re.R. | Pirelli: 5 mm |
| Tyre profile depth FL | | | | 5 |
| Tyre profile depth FR | | | | 5 |
| Tyre profile depth RL | | | | 5 |
| Tyre profile depth RR | | | | 5 |
| Tyre size FL | | | | 245/50 R 19 92 MS |
| Tyre type FL | | | | Winter |
| Tyre make FL | | | | 264 |
| Tyre make RL | | | | 264 |

Assistance equipment

| | | | |
|--|----------|---------|------------|
| Number of charging cables (normal) | 0 | Runflat | Yes |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|--------------------------|--------------|
| Total cost ex VAT | 64,68 |
|--------------------------|--------------|

| | |
|---|--------------|
| Windscreen, Stone chip(s), Windscreen repair | 64,68 |
|---|--------------|

