



**LAND ROVER RANGE ROVER EVOQUE: 1SRV751**

Vinnumber:	<b>SALVA2BN4HH224109</b>	Versionname:	<b>TD4 110kW SE Dynamic 4WD Auto</b>
First Registrationdate:	<b>29/06/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>66396</b>	Power Kw:	<b>110</b>
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>2425</b>
Fueltype:	<b>Diesel</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>No</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

**Options**

Number of keys total	<b>2</b>	Seats electric F L	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	<b>Tow bar removable</b>
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Degree of wear**

<b>235/69/18/103 V</b>				
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>
Tyre profile depth FL				<b>4</b>
Tyre profile depth FR				<b>4</b>
Tyre profile depth RL				<b>4</b>
Tyre profile depth RR				<b>4</b>
Tyre size FL				<b>235/69 R 18 103 V</b>
Tyre type FL				<b>Winter</b>
Tyre make FL				<b>261</b>
Tyre make RL				<b>261</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT 1536,59

Door RR, Scratch(es), Repair and paint (complete) 0,00



Bumper F, Scratch(es), Spot repair 127,12



Tailgate / Boot, Not original part, Acceptable

0,00



Boot carpet, Dirty, Cleaning

25,00



Door panel RR, Scratch(es), Replace

158,60



Bonnet, Chemical polution, Repair and paint (complete)

417,70



Rear window, Scratch(es), Replace

0,00



Door FR, Scratch(es), Repair and paint (complete)

458,42



Backrest cover FL, Scratch(es), Smart repair

70,75



Alloy rim RR, Scratch(es), Repair and paint (complete)

114,00



Door trim RR, Scratch(es), Smart repair

0,00



Certificate Of Conformity, Missing, Replace

165,00

No pictures to display