



Porsche Panamera: 1WCB652

| | | | |
|-------------------------------------|--------------------------|-------------------------|------------------|
| Vinnumber: | WP0ZZZ97ZJL175925 | Versionname: | |
| First Registrationdate: | 5/11/2018 | Fiscalpower: | |
| Expertise Mileage: | 136668 | Power Kw: | 243 |
| Bodytype: | | Body colour: | Blue |
| Gearbox: | Automatic | Type of rims (mounted): | Aluminium |
| Transmission: | | Parking lot: | 1513 |
| Fueltype: | Hybrid Petrol | | |
| Maintenance: | NOT OK | | |
| Type of rims (mounted): | Aluminium | | |
| Certificate of Conformity: | Yes | | |
| Category: | Passenger Car | | |
| Registration Certificate Car (BE): | Yes | | |
| Registration Certificate Home (BE): | Yes | | |

Options

| | | | |
|---------------------------------|------------------------------|------------------------|-------------------|
| Number of keys total: | 2 | Seats electric F L: | |
| Cruise Control: | | Seats electric F R: | |
| Steering wheel multifunctional: | | Sun Roof electric: | |
| Type of headlighting: | Headlighting LED | Panoramic roof: | |
| Type of GPS: | GPS big screen color | Luggage cover: | |
| Type of Lining: | Lining leather | Front parking sensors: | |
| Type of climate control: | Autom climate control | Rear parking sensors: | |
| Sport seats: | | Type of Tow bar: | No Tow bar |

Limited Technical Inspection

Degree of wear

| | | | | |
|------------------------|-----------------------|----------------------|-------|-------------------------|
| | 315/30/21/10 Y | | | |
| Summer tyres: | Fr.L. | Hankook: 5 mm | Fr.R. | Hankook: 5 mm |
| | Re.L. | Hankook: 5 mm | Re.R. | Hankook: 5 mm |
| Tyre profile depth FL: | | | | 5 |
| Tyre profile depth FR: | | | | 5 |
| Tyre profile depth RL: | | | | 5 |
| Tyre profile depth RR: | | | | 5 |
| Tyre size FL: | | | | 315/30 R 21 10 Y |
| Tyre type FL: | | | | Summer |
| Tyre make FL: | | | | 260 |
| Tyre make RL: | | | | 260 |

Assistance equipment

| | |
|---|----------|
| Number of charging cables (normal): | 0 |
| Number of charging cables (rapid charge): | 0 |

| | |
|---|----------------|
| Total cost ex VAT | 2324,98 |
| Alloy rim FL, Scratch(es), Repair and paint (complete) | 114,00 |



| | |
|---|--------------|
| Bumper spoiler F, Scratch(es), Replace | 57,70 |
|---|--------------|



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)

391,99



Door RR, Scratch(es), Acceptable

0,00



Alloy rim RL, Scratch(es), Replace

307,78



Door FR, Chemical polution, Acceptable

0,00



Charging cable (normal), Missing, Replace

550,00



Tyre RL, Tear, Replace

184,52



Alloy rim RR, Scratch(es), Repair and paint (complete)

114,00



Service, Maintenance, Check

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), Repair and paint (complete)

304,99



Wing FL, Scratch(es), Acceptable

0,00



Tailgate / Boot, Scratch(es), Acceptable

0,00



Charging cable (fast), Missing, Replace

300,00

