



<b>Toyota C-HR: 1VBU566</b>			
Vinnumber:	<b>NMTKZ3BX60R184804</b>	Versionname:	
First Registrationdate:	<b>18/09/2018</b>	Fiscalpower:	
Expertise Mileage:	<b>108792</b>	Power Kw:	<b>72</b>
Bodytype:		Body colour:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>2829</b>
Fueltype:	<b>Hybrid Petrol</b>		
Maintenance:	<b>OK</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>Yes</b>		

<b>Options</b>			
Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	<b>No Tow bar</b>
Type of headlighting:	<b>Headlighting LED</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining semi-artificial leather</b>		
Type of climate control:	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Degree of wear**

<b>225/50/18/92 H</b>			
Winter tyres:	Fr.L. <b>Bridgestone: 5 mm</b>	Fr.R. <b>Bridgestone: 5 mm</b>	
	Re.L. <b>Bridgestone: 5 mm</b>	Re.R. <b>Bridgestone: 5 mm</b>	
Tyre profile depth FL:			<b>5.0</b>
Tyre profile depth FR:			<b>5.0</b>
Tyre profile depth RL:			<b>5.0</b>
Tyre profile depth RR:			<b>5.0</b>
Tyre size FL:			<b>225/50 R 18 92 H</b>
Tyre type FL:			<b>Winter</b>
Tyre make FL:			<b>255</b>
Tyre make RL:			<b>255</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

<b>Total cost ex VAT</b>	<b>2739,24</b>
--------------------------	----------------

<b>Wing trim FR, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------



<b>Door trim RR, Scratch(es), Replace</b>	<b>137,00</b>
---	---------------



Wing RR, Scratch(es), Acceptable

0,00



Wing FL, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Repair and paint (complete)

254,16



Door panel RR, Scratch(es), Replace

137,00



Door RL, Scratch(es), Acceptable

0,00



Door RR, Scratch(es), Repair and paint (complete)

382,02



Wing trim RR, Scratch(es), Replace

101,00



Bumper F, Scratch(es), Repair and paint (complete)

254,16



Bumper trim R, Scratch(es), Replace

256,79



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 175,00



Rear light L, Scratch(es), Polish 0,00



Bonnet, Chemical polution, Repair and paint (complete) 348,09



Door FL, Scratch(es), Repair and paint (complete) 382,02



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 175,00



Door panel RL, Scratch(es), Replace 137,00

