



Peugeot 308: 1UPD739

Vinnumber:	VF3LBYHZPJ5279355	Versionname:	
First Registrationdate:	28/06/2018	Fiscalpower:	
Expertise Mileage:	159796	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2826
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Panoramic roof	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining leather and alcantara		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Degree of wear

205/55/16/91 H				
Winter tyres:	Fr.L.	Semperit: 3 mm	Fr.R.	Semperit: 3 mm
	Re.L.	Other: 7 mm	Re.R.	Other: 7 mm
Tyre profile depth FL		3.0		
Tyre profile depth FR		3.0		
Tyre profile depth RL		7.0		
Tyre profile depth RR		7.0		
Tyre size FL		205/55 R 16 91 H		
Tyre type FL		Winter		
Tyre make FL		2477		
Tyre make RL		263		

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2406,75
Alloy rim RL, Scratch(es), Repair and paint (complete)	125,40



Door FL, Scratch(es), Spot repair	139,83
-----------------------------------	--------



Door FR, Dent(s) and scratch(es), Repair and paint (complete)

420,22



Alloy rim FR, Scratch(es), Repair and paint (complete)

125,40



Alloy rim FL, Scratch(es), Repair and paint (complete)

125,40



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)

398,21



Roof liner, Stain, Cleaning

27,50



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)

152,53



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)

290,63



Bumper F, Scratch(es), Spot repair

139,83



Seat cover FL, Tear, Replace

461,80

