



LU Skoda Superb Combi: VT7941

Vinnumber:	TMBLJ9NP5L7024598	Versionname:	2.0 TDI 140kW L&K DSG 4x4
First Registrationdate:	2/12/2019	Fiscalpower:	
Expertise Mileage:	134093	Power Kw:	140
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3509
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Seats electric F L	
Steering wheel multifunctional		Seats electric F R	
Seats F heated		Sun Roof electric	
Radio multimedia		Panoramic roof	
Type of headlighting	Headlighting LED	Luggage cover	
Type of GPS	GPS big screen color	Front parking sensors	
Type of Lining	Lining leather	Rear parking sensors	
Type of climate control	Autom climate control	Type of Tow bar	Tow bar collapsible
Adaptive cruise control			
Type of GPS storage	HD		

Limited Technical Inspection

Degree of wear

235/40/19/98 W				
Winter tyres:	Fr.L.	Pirelli: 4,2 mm	Fr.R.	Pirelli: 4,2 mm
	Re.L.	Pirelli: 4,8 mm	Re.R.	Pirelli: 4,8 mm
Tyre profile depth FL				4.2
Tyre profile depth FR				4.2
Tyre profile depth RL				4.8
Tyre profile depth RR				4.8
Tyre size FL				235/40 R 19 98 W
Tyre type FL				Winter
Tyre make FL				264
Tyre make RL				264

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	4291,41
Door FL, Scratch(es), Acceptable	0,00





Bumper F, Scratch(es), Repair and paint (complete)

335,48



Windscreen, Crack, Replace

678,17



Outer door handle FL, Scratch(es), Acceptable

0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete)

192,50



Bumper moulding F, Broken, Replace

187,40



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

192,50



Door FR, Dent(s), Repair and paint (complete)

504,26



Alloy rim RL polished, Scratch(es), Repair and paint (complete)

192,50



Bumper R, Scratch(es), Repair and paint (complete)

335,48



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

192,50



Door RL, Dent(s) and scratch(es), Repair and paint (complete)

504,26



Tailgate / Boot, Scratch(es), Acceptable

0,00



Bonnet, Stone chip(s), Acceptable

0,00



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)

488,18

