



**BMW 1 HATCH: QH8401**

Vinnumber:	<b>WBA7K310507G92496</b>	Versionname:	<b>118iA (103 kW)</b>
First Registrationdate:	<b>22/10/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>34282</b>	Power Kw:	<b>103</b>
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>parking vrachtwagens</b>
Fueltype:	<b>Petrol</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>VS</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	<b>No Tow bar</b>
Type of headlighting:	<b>Headlighting LED</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Autom climate control</b>		
Type of GPS storage:	<b>HD</b>		

**Limited Technical Inspection**

**Degree of wear**

	<b>205/55/16/91 H</b>			
Winter tyres:	Fr.L.	<b>Continental: 6 mm</b>	Fr.R.	<b>Continental: 6 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 7 mm</b>
Tyre profile depth FL				<b>6.0</b>
Tyre profile depth FR				<b>6.0</b>
Tyre profile depth RL				<b>7.0</b>
Tyre profile depth RR				<b>7.0</b>
Tyre size FL				<b>205/55 R 16 91 H</b>
Tyre type FL				<b>Winter</b>
Tyre make FL				<b>256</b>
Tyre make RL				<b>256</b>

**Assistance equipment**

Number of charging cables (normal):	<b>0</b>	Runflat:	<b>No</b>
Number of charging cables (rapid charge):	<b>0</b>		

<b>Total cost ex VAT</b>	<b>1363,16</b>
--------------------------	----------------

<b>Door FR, Dent(s) and scratch(es), Repair and paint (complete)</b>	<b>420,22</b>
--	---------------



<b>Door RR, Dent(s) and scratch(es), Repair and paint (complete)</b>	<b>420,22</b>
--	---------------



Outer sill L, Scratch(es), Spot repair 139,83



Bumper moulding F, Scratch(es), Acceptable 0,00



Wing RL, Scratch(es), Acceptable 0,00



Tailgate / Boot, Scratch(es), Paint (partial) 0,00



Bonnet, Scratch(es), Repair and paint (complete) 382,89

