



VOLKSWAGEN TOURAN: 1WBR261

Vinnumber:	WVGZZZ1TZKW052879	Versionname:	1.6 TDi Trendline
First Registrationdate:	16/04/2019	Fiscalpower:	
Expertise Mileage:	181346	Power Kw:	85
Bodytype:		Body colour	Red
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel
Transmission:		Parking lot	4613
Fueltype:	Diesel		
Maintenance	OK		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	Yes		

Options

Number of keys total	2	Sun Roof electric	
TV/DVD screen F		Panoramic roof	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			
Type of GPS storage	SD present		

Limited Technical Inspection

Degree of wear

205/60/16/96 H				
Winter tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 6 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				6.0
Tyre profile depth RL				7.0
Tyre profile depth RR				6.0
Tyre size FL				205/60 R 16 96 H
Tyre type FL				Winter
Tyre make FL				2480
Tyre make RL				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1082,69
Door FR, Scratch(es), Acceptable	0,00



Tailgate / Boot, Scratch(es), Acceptable

0,00



Bonnet, Scratch(es), Repair and paint (complete)

382,89



Door FL, Scratch(es), Acceptable

0,00



Wheel cover FL, Scratch(es), Acceptable

0,00



Wheel cover FR, Scratch(es), Acceptable

0,00



Wheel cover RR, Scratch(es), Replace

39,60



Wing FR, Scratch(es), Repair and paint (complete)

290,63



Wing FL, Scratch(es), Acceptable

0,00



Wing RR, Dent(s), Paintless dent repair

90,00



Wing RL, Dent(s), Acceptable

0,00



Bumper F, Scratch(es), Repair and paint (complete)

279,57



Bumper R, Scratch(es), Acceptable

0,00

