

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	153187 KM
File nr. :	1435933	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EEJ993 / VF30A9HR8CS237981 /		yr of constructionr :	/
E-File nr. :		First registration :	07/11/2012
VFS-nr. :		Color :	BLACK
Make + Model :	PEUGEOT / 5008	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	EDF LUMINUS	Co2:	135g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	5 [x]
Vehicle type :	5008 Active FAP 112PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	112	kW:	82
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	1.6-2/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	1.6-2/	Rim :	/	Hubcap :
Wheel RES:	[x]	ANDERE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	V
Rear tyre	215	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	WINDOW STYLE/REAR DOOR/LEF	OTHER DAMAGES
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS

Interior

[x]	STEERING WHEEL	OTHER DAMAGES
[x]	CARPET FL	HOLE
[x]	BOOT LID IN	SCRATCHED

Accessories and others

[x]	OUTSIDE MIRROR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	OUTSIDE MIRROR RIGHTHAND SIDE	OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/CORNER	HOLE/CRACK/TORN	REEDS AANGEG.			
		Repair paint - LI	New paint - E	Depr.	Total	
5	15 LU =72.00 EUR	0 EUR	235.80 EUR	50 %	307.80 EUR	
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT	+KRAS			
		Repair paint - LI	New paint - E	Depr.	Total	
6	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR	
[x]	REAR DOOR/RIGHT/CENTER	DENT	+KRAS			
		Repair paint - LI	New paint - E	Depr.	Total	
6	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR	
[x]	WINDSCREEN/LEFT	WINDOW DAMAGE				
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR

[x]	FRONT MUDGUARD/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR
[x]	FRONT BUMPER/RIGHT/SIDE		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Interior

[x]	FLOOR FL		BURNT			
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-inttap-01	CARPET REPAIR (MAX 3CM LENGTH OR DIAMETER)	43.92 EUR		43.92 EUR
[x]	SEAT FL		BURNT			
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-intvlr-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER)	64.32 EUR		64.32 EUR
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-intvlr-02	SUPL VELLOURS REPAIR	18.00 EUR		18.00 EUR
[x]	ROOF UPHOLSTERY		BURNT			
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-intvlr-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER)	64.32 EUR		64.32 EUR

Pieces

	Number	Code	Description	Unit price	Depr.	Total
5	1	REAR BUMPER		343.20 EUR	50 %	343.20 EUR

1	2	3	4	5	6	7	8	9	10
58.80	190.56	211.80	220.18	651.00	626.55	0	0	0	0
58.80	190.56	105.90	110.09	325.50	313.28	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
249.36	1709.53	0	1958.89
HOG: 0	BG: 0		NA Deprec. 1104.12
			0.00%
			TOTAL 1104.12

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/09/2017 Hour : 13:36 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	