

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	9788 KM
<b>File nr. :</b>	1434865	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1PNU669 / JTDKB3FU403504158 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	17/08/2016
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	TOYOTA / PRIUS	<b>Fuel type :</b>	HYBRID
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 6
<b>Customer company :</b>	TIETO NORWAY AS	<b>Co2:</b>	79g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1798
<b>Gear box :</b>	Automaat algemeen	<b>Number of places:</b>	5
<b>Number of gears:</b>		<b>Number of doors:</b>	5
<b>HP:</b>	98	<b>kW:</b>	72
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	NOK	[x]		
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	NOK	[x]	MISSING/INCOMPLETE
Cert. of reg. copy / Part 2:		Insurance certificate :				
Warning vest :	OK	[x]	Transport licence :			
Tax certificate :		Navigation CD/SD/DVD	OK	[x]		
Fuel card :		Car radio :	OK	[x]		
Mobile phone kit :		Extinguisher :	OK	[x]		
First aid kit :	OK	[x]	Warning triangle :	OK	[x]	
Jack, wheelspanner :	OK	[x]	Oil level :	OK	[x]	
		Filled up :	0			

## Wheels and tyres: Summer tires

Wheel FL:	[x]	TOYO	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel RL :	[x]	TOYO	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel FR :	[x]	TOYO	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RR :	[x]	TOYO	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	215	45	R	17	W
Rear tyre	215	45	R	17	W

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT		SCRATCH WITH PAINT DAMAGE	MEERDERE	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x]	FRONT BUMPER/RIGHT		SCRATCH WITH PAINT DAMAGE		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

### Others

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	211.80	95.00	0	0	0	0	0	0	0
105.90	105.90	95.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	423.60	0	<b>518.60</b>
HOG: 0	BG: 0		NA Deprec. 306.80
			0.00%
			<b>TOTAL 306.80</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 08/09/2017 <b>Hour :</b> 15:48 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	