

**Make :** VOLKSWAGEN  
**Type :** GOLF BREAK  
**Reference / Registration :** /1HGF135  
**Mls :** 191539

**Client :** KBC REMARKETING  
**Date :** 18/09/2017

<b>OK</b>	<b>NOK</b>	<b>ENGINE:</b>	<b>Remark</b>
X		STARTING CAPACITY	
X		NOISES:	
X		STATIONARY REGIME	
X		SMOKE	
X		OIL LEVEL	
X		BRAKE FLUID	
X		OIL LEVEL	
X		WIPER FLUID LEVEL	
X		NEXT SERVICE	
X		BATTERY	

  

<b>OK</b>	<b>NOK</b>	<b>CLUTCH-GEARBOX</b>	<b>Remark</b>
X		CLUCH TEST	
X		GEARBOX FUNCTIONING	
X		NOISES	

  

<b>OK</b>	<b>NOK</b>	<b>AIRCO:</b>	<b>Remark</b>
X		START COMPRESSOR	
X		COLD AIR FLOW	

  

<b>OK</b>	<b>NOK</b>	<b>POWER STEERING:</b>	<b>Remark</b>
X		POWER STEERING	

  

<b>OK</b>	<b>NOK</b>	<b>HAND BRAKE:</b>	<b>Remark</b>
X		OPERATION HAND BRAKE	

OK	NOK	TYRES:	Remark
X		TREAD FRONT	
X		TREAD REAR	
X		PRESSURE	
X		TREAD WEAR	

OK	NOK	VISIBILITY:	Remark
X		WIPERS	
X		LIGHTING	