

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	155172 KM
File nr. :	1444127	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DXM702 / VF30U9HR8CS213903 /		yr of constructionr :	/
E-File nr. :		First registration :	26/09/2012
VFS-nr. :		Color :	GREY
Make + Model :	PEUGEOT / 3008	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KBC GROEP NV	Co2:	130g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3008 Active FAP 112PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	112	kW:	82
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	>6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	V
Rear tyre	225	50	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

Conclusion

Bodywork \& windows

[x] WINDSCREEN/RIGHT OTHER DAMAGES OVBH

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/RIGHT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR DOOR/RIGHT/FRONT SCRATCH (WITHOUT PAINT DAMAGE) OVBH POL.

[x] BONNET/CENTER/LEFT/FRONT CHIPS

[x] FRONT BUMPER/RIGHT/SIDE SCRATCH (WITHOUT PAINT DAMAGE)

Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	REEDS AANGEGEVEN=VANDALISME		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	301.68 EUR		50 %	301.68 EUR

[x]	REAR BUMPER/SIDE/LEFTCENTER	SCRATCH WITH PAINT DAMAGE	REEDS AANGEGEVEN=VANDALISME		
		Repair paint - LI	New paint - E	Depr.	Total
3	11 i-vab-sp-01	SPOTREPAIR		50 %	115.56 EUR

[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	REEDS AANGEGEVEN=VANDALISME		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	REEDS AANGEGEVEN=VANDALISME		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x]	FRONT DOOR/LEFT/FRONT		DENT		REEDS AANGEGEVEN
		Repair paint - LI	New paint - E	Depr.	Total
2	25 LU =120.00 EUR	318.35 EUR		50 %	438.35 EUR
[x]	FRONT MUDGUARD/LEFT/REAR		SCRATCH WITH PAINT DAMAGE		REEDS AANGEGEVEN
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

Interior

[x]	SEAT FL		STAIN			
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE		SCRATCH WITH PAINT DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

Others

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
14.58	869.09	1043.79	0	0	0	0	0	0	0
14.58	539.82	521.90	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
340.70	1586.76	0	1927.46
HOG: 0	BG: 0		NA Deprec. 1076.30
			0.00%
			TOTAL 1076.30

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 03/10/2017 Hour : 15:22 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	