


BMW 3: 1EGT757

Vinnnumber:	WBA3K11090F817165	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	28/11/2012	Fiscalpower:	
Expertise Mileage:	89964	Power Kw:	100
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3431
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/16/95 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	15,00
-------------------	--------------

Door panel R R, Scratch(es), Acceptable	0,00
-----------------------------------------	-------------

No pictures to display

Bumper R, Damaged, Le - Replace and paint	0,00
-------------------------------------------	-------------





Rocker panel inner R R, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wheel hub cap R L, Missing, E - Replace 15,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display