



| LAND ROVER Evoque: 1EPK821 | | | |
|----------------------------|--------------------------|--------------|------------------------|
| Vinnumber: | SALVB2DC2DH759118 | Versionname: | D4 2WD Prestige |
| First Registrationdate: | 14/02/2013 | Fiscalpower: | |
| Expertise Mileage: | 172641 | Power Kw: | 110 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1310 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 4 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

| Options | | | |
|--------------------------------|------------------------------|-----------------------|----------------------|
| GPS storage | | Seats electric F L | |
| GPS storage | HD | Seats electric F R | |
| Windows electric F | | Central consol F | |
| Windows electric R | | Luggage cover | |
| Cruise Control | | Front parking sensors | |
| Steering wheel multifunctional | | Rear parking sensors | |
| Radio multimedia | | Type of Tow bar | Tow bar fixed |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |
| Level control | | | |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| Degree of wear | | | | |
|----------------|-----------------------------------|--------------------------|-------|--------------------------|
| | 235/55/19/105 V LightMetal | | | |
| Summer tyres: | Fr.L. | Continental: 5 mm | Fr.R. | Continental: 5 mm |
| | Re.L. | Continental: 6 mm | Re.R. | Continental: 6 mm |

| Assistance equipment | | | |
|---|------------|------------|----------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 2016,11 |
| Door trim R L, Scratch(es), E - Replace | | | 114,00 |



| | | | |
|--|--|--|---------------|
| Trunk lid covering R, Scratch(es), E - Replace | | | 115,11 |
|--|--|--|---------------|



Bumper trim R, Bump(s) and scratch(es), E - Replace

417,20



Bodywork, Damaged, Acceptable

0,00



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)

462,35



Interior, Worn, Acceptable

0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Reflector, Broken, E - Replace

118,21



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)

349,68



Boot cover, Incomplete, E - Replace

50,00





Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing trim R L, Scratch(es), E - Replace 84,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56

