



TOYOTA AURIS: 1NTG687

Vinnnumber:	SB1MS3JE00E243208	Versionname:	1.8 HYBRID LOUNGE CVT AUTO
First Registrationdate:	21/04/2016	Fiscalpower:	
Expertise Mileage:	31428	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	1308
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics

Limited Technical Inspection

Airco functioning:	OK	Battery functioning:	Yes
Tires wear profile:	OK	Power steering:	Yes
Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Wiper fluid level:	OK
Handbrake:	OK	Transmission:	OK
		Lighting:	OK
		Wiperblades:	OK

Degree of wear

	225/45/17/92 H LightMetal			
Summer tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
-------------	------------	-------------	------------

Total cost ex VAT:	1157,40
Alloy rim F L, Scratch(es), LI - Repair and paint (complete):	95,00



Windscreen, Stone chip(s), E - Replace:	487,20
---	---------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete):	95,00
---	--------------



Wing F R, Scratch(es), Acceptable 0,00



Ignition key, Missing, E - Replace 150,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Damaged, E - Replace 235,20



Door F R, Scratch(es), Acceptable 0,00

