



LU Porsche 911 LU: QK7259

Vinnumber:	WPOZZZ99ZGS138149	Versionname:	3.4 CARRERA CABRIOLET
First Registrationdate:	30/07/2015	Fiscalpower:	
Expertise Mileage:	41606	Power Kw:	257
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2723
Number of doors:	2		
Number of seats:	4		
Number head rests:	2		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Sun Roof electric	
Windows electric F		Central consol F	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

285/35/19/103 Y LightMetal				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1508,76
-------------------	----------------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Tyre R R, Tear, E - Replace 153,60



Wing R R, Scratch(es), Acceptable 0,00



Backrest cover F R, Scratch(es), E - Replace 408,00



Wing R L, Scratch(es), Acceptable 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Stone chip(s), Acceptable 0,00



Windscreen, Repaired, Acceptable 0,00



Seat cover R R, Tear, E - Replace 408,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

