



RENAULT Trafic: 1HKG491

Vinnumber:	VF1FLB1B8EY783122	Versionname:	TRAFIC 29 B/F L2H1 Gr.Conf.FAP(EU5)115PK
First Registrationdate:	8/08/2014	Fiscalpower:	
Expertise Mileage:	214390	Power Kw:	84
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV13
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/106 T Steel				
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1593,71
Wheel cover R L, Missing, E - Replace	22,50



Bumper F, Dent(s), E - Replace	398,40
---------------------------------------	---------------



Trunk door R L, Dent(s), Acceptable 0,00

No pictures to display

Roof, Dent(s), LI - Repair and paint (complete) 361,13



Wheel cover F R, Missing, E - Replace 22,50



Wheel cover R R, Missing, E - Replace 22,50



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper corner R R, Scratch(es), Smart repair 110,64



Windscreen, Scratch(es), E - Replace 395,40



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s), Smart repair 110,64



Ignition key, Missing, E - Replace 150,00

No pictures to display