



VOLKSWAGEN SHARAN: 1LJP454

Vinnumber:	WVWZZZ7N2GV213739	Versionname:	2.0 CR TDI 110KW HIGHLINE BMT
First Registrationdate:	6/10/2015	Fiscalpower:	
Expertise Mileage:	171900	Power Kw:	110
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4832
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/18/92 MS LightMetal				
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Total cost ex VAT	759,72
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Rear wiper arm, Incomplete, E - Replace 5,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Rear window, Scratch(es), Acceptable 0,00



Windscreen, Scratch(es), Acceptable 0,00



Airco control, Missing, E - Replace 5,00



Bumper F L, Scratch(es), It - Spot repair 115,56

