



LEXUS UX: 1YFM031

Vinnumber:	JTHY65BH402059881	Versionname:	2.0L 250H Business Line Plus
First Registrationdate:	13/08/2020	Fiscalpower:	
Expertise Mileage:	77103	Power Kw:	135
Bodytype:		Body colour	Blue
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2402
Fueltype:	Hybrid Petrol		
Maintenance	over 12124 km		
Maintenance	OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Degree of wear

215/60/17/96 H				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				215/60 R 17 96 H
Tyre type FL				Summer
Tyre make FL				255
Tyre make RL				255

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	501,52
-------------------	--------

Alloy rim FR, Scratch(es), Repair and paint (complete)	114,00
--	--------



Covering interior C pillar L, Scratch(es), Smart repair

127,12



Wing trim FR, Scratch(es), Replace

49,73



Boot carpet, Stain, Acceptable

0,00



Rear light L, Scratch(es), Acceptable

0,00



Door FR, Scratch(es), Acceptable

0,00



Alloy rim RR, Scratch(es), Acceptable

0,00



Outside rear-view mirror L, complete, Scratch(es), Acceptable

0,00



Door RL, Dent(s) and scratch(es), Acceptable

0,00



Outside rear-view mirror housing R, Scratch(es), Acceptable

0,00



Outer door handle FR, Scratch(es), Repair and paint (complete)	138,67
--	--------



Bumper F, Scratch(es), Polish	0,00
-------------------------------	------



Boot cover, Missing, Replace	72,00
------------------------------	-------

