



TOYOTA AURIS TOURING SPORTS: 1VCY778			
Vinnumber:	SB1Z53JE50E450232	Versionname:	1.8 VVT-i Hybrid CVT Business Plus
First Registrationdate:	28/09/2018	Fiscalpower:	
Expertise Mileage:	92083	Power Kw:	100
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2823
Fueltype:	Hybrid Petrol		
Maintenance	OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options			
Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Degree of wear

Summer tyres:	195/65/15/91 H			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				195/65 R 15 91 H
Tyre type FL				Summer
Tyre make FL				261
Tyre make RL				261

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	573,02
Door RL, Scratch(es), Repair and paint (complete)	382,02



Bumper moulding F, Missing, Replace	0,00
-------------------------------------	------



Boot lid covering R, Scratch(es), Smart repair

121,70



Bumper R, Scratch(es), Acceptable

0,00



Bumper moulding F, Broken, Replace

0,00



Alloy rim RR, Scratch(es), Acceptable

0,00



Wing FL, Dent(s), Paintless dent repair

69,30



Wing FR, Scratch(es), Acceptable

0,00



Bumper F, Broken, Replace and paint

0,00

