

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	56986 KM
File nr. :	1376075	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FOV022 / WAUZZZ8X3EB016155 /		yr of constructionr :	2013 / 00
E-File nr. :		First registration :	10/09/2013
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / A1 SPORTBACK	Fuel type :	DIESEL
Object nr. :	32588	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ERNST & YOUNG BEDRIJFSREVISOREN CVBA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	A1 SB Attraction 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	
Number of gears:	5	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	15	WINTER H
Rear tyre	205	55	R	15	WINTER H

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	WINDSCREEN/CENTER/LEFT	CHIPS	MEERDERE
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	MEERDERE
[x]	FRONT BUMPER/CENTER/LEFT	CHIPS	
[x]	FRONT BUMPER/CENTER/RIGHT	CHIPS	

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	MEERDERE	
	Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	169.44 EUR	50 %	169.44 EUR

Others

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
169.44	95.00	0	0	0	0	0	0	0	0
84.72	95.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	169.44	0	264.44
HOG: 0	BG: 1		NA Deprec. 179.72
			0.00%
			TOTAL 179.72

APPRAISAL

www.vabfleetservices.be

Date : 10/03/2017

4/4

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min	Towing time : 0 min
	Reason :	Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 10/03/2017 Hour : 10:22	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	