

www.vabfleetservices.be Date: 12/04/2017 1/4

AU4P1X

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	111275 KM
File nr. :	1388304	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DGS941 / WAUZZZ8K9DA0	054448 /	yr of constructionr :	/
E-File nr. :		First registration :	11/05/2012
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / A4 AVANT	Fuel type :	DIESEL
Object nr. :	61120	Fuel:	
Classification:	F	Environment Class:	EURO 5
Customer company :	CLINIQUES SAINT LUC ASBL	Co2:	116g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A4 AVANT TDie 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	



www.vabfleetservices.be Date: 12/04/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK		Insurance certificate :		
Warning vest:	OK	[x]	Transport licence :		
Tax certificate:			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Rea	r tvre		20	05				60			R		16	WINTER H
Fro	nt tyre		20	05			(60			R		16	WINTER H
		[x]	Wi	idth			Не	eight			Type		Rim	Index
Wheel RES:	[x]			Tyre:		OK		/	Rim:			/	Hubcap:	
Wheel RR:	[x]	PIRELI	LI	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED) /	Hubcap:	
Wheel FR:	[x]	CONTI	NENTAL	Tyre:	[x]	OK	[x]	4-6 /	Rim:			/	Hubcap:	
Wheel RL:	[x]	PIRELI	LI	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	,	Hubcap:	
Wheel FL:	[x]	CONTI	NENTAL	Tyre:		OK	[x]	4-6 /	Rim:			/	Hubcap:	

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:

Remark:



www.vabfleetservices.be Date: 12/04/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT MUDGUARD/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

[x] FRONT MUDGUARD/RIGHT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

:]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE	MEERDERE	
		Repair paint - LI	New paint - E	Depr.	Total
	2 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
:]	FRONT BUMPER/RIGHT/SIDE		SCRATCH WITH PAINT DAMAGE	MEERDERE	
		Repair paint - LI	New paint - E	Depr.	Total
	1 0 LU =0.00 EUR	211.80 EUR	'	50 %	211.80 EUR

Others

[x]

[x]

RIM REAR LEFT

]	Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	211.80	95.00	0	0	0	0	0	0	0
105.90	105.90	95.00	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
518.60		0	423.60	95.00
306.80	NA Deprec.		BG: 0	HOG: 0
	0.00%			
306.80	TOTAL			



12/04/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES			UNDER CONDITION - DUSTY VEHICLE				
Extra Time :	0 min	Waiting time: 0 mi Reason:	in	Towing time : Reason :	0 min		
NOT EXECUTED Reason:): No	_		.			
Remark:							
Prices in EUR	without VAT						
Authorized by customer:			Executed by VAB Fleet S	Services			
Remark authorize	d customer :						
Date :	12/04/2017	Hour: 16:18					
Company :							
Executed by VAB Services	Fleet						
E-Mail :	@						
Signature authorize	d by customer						