

AR9KKF

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	142775 KM
File nr. :	1386164	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EEO288 / WAUZZZ8KXDA137757 /		yr of constructionr :	/
E-File nr. :		First registration :	08/11/2012
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / A4 AVANT	Fuel type :	DIESEL
Object nr. :	61158	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	COLLIBRA NV	Co2:	123g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A4 AVANT TDi 120PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	120	kW:	88
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	>6 /	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6 /	Rim :	/
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	>6 /	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	16	V
Rear tyre	225	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE		MEERDERE		
			Repair paint - LI	New paint - E	Depr.		Total
2	0	LU =0.00 EUR	211.80 EUR				211.80 EUR
[x]	FRONT BUMPER/LEFT/SIDE		SCRATCH WITH PAINT DAMAGE				
	Number	Code	Description	Unit price	Depr.		Total
0	0						
[x]	FRONT BUMPER/RIGHT/SIDE		SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.		Total
1	0	LU =0.00 EUR	211.80 EUR		50 %		211.80 EUR

Interior

[x]	SEAT REAR L		STAIN				
	Number	Code	Description	Unit price	Depr.		Total
3	1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR			14.58 EUR

1	2	3	4	5	6	7	8	9	10
211.80	211.80	14.58	0	0	0	0	0	0	0
105.90	211.80	14.58	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
14.58	423.60	0	438.18
HOG: 0	BG: 0		NA Deprec. 332.28
			0.00%
			TOTAL 332.28

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 11/04/2017 Hour : 16:21 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	