

ASIT8U

☒ EFFECTIVE    ☐ NOT EXECUTED    ☒ COLLECTION    ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	105717 KM
File nr. :	1387092	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FET448 / WAUZZZ8K0DA254800 /		yr of constructionr :	/
E-File nr. :		First registration :	10/06/2013
VFS-nr. :		Color :	BLACK
Make + Model :	AUDI / A4 AVANT	Fuel type :	DIESEL
Object nr. :	33860	Fuel :	
Classification :	F	Environment Class:	EURO 5
Customer company :	HARVARD ENGINEERING PLC	Co2:	123g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A4 AVANT TDi 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	[x]	Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
First aid kit :	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	1.6-2 /	Rim :	/	Hubcap :
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	1.6-2 /	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	1.6-2 /	Rim :	/
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	1.6-2 /	Rim :	/	Hubcap :
Wheel RES:	[x]	ANDERE	Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	Y
Rear tyre	225	50	R	17	Y

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Accessories and others

[x] OUTSIDE MIRROR LEFTHAND SIDE

SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x] REAR BUMPER /LEFT/CORNER

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x] REAR DOOR/RIGHT/CENTER

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] FRONT MUDGUARD/LEFT/FRONT

SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

[x] FRONT BUMPER/RIGHT/SIDE

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	115.56	211.80	318.35	0	0	0	0	0	0
105.90	115.56	105.90	159.18	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
115.56	741.95	0	857.51
HOG: 0	BG: 0		NA Deprec. 486.54
			0.00%
			TOTAL 486.54

# APPRAISAL

**www.vabfleetservices.be**

**Date : 11/04/2017**

4/4

**[x] = Status Modification**

**Pictures :** No

## CIRCUMSTANCES

### UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min	Towing time : 0 min
	Reason :	Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

**Prices in EUR without VAT**

<b>Authorized by customer :</b>	Executed by VAB Fleet Services
<b>Remark authorized customer :</b>	
<b>Date :</b> 11/04/2017 <b>Hour :</b> 11:42	
<b>Company :</b> <b>Executed by VAB Fleet Services</b> <b>E-Mail :</b> @	
<b>Signature authorized by customer</b> 	