

AQVE88

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	161204 KM
File nr. :	1385855	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GKI457 / WAUZZZ8T3EA051264 /		yr of constructionr :	/
E-File nr. :		First registration :	03/03/2014
VFS-nr. :		Color :	WHITE
Make + Model :	AUDI / A5 SPORTBACK	Fuel type :	DIESEL
Object nr. :	44626	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ALSTOM BELGIUM	Co2:	1129g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1968
Gear box :	Manueel	Number of places:	4
Number of gears:	6	Number of doors:	5
HP:	150	kW:	110
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:			Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK		/	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK		/	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	H
Rear tyre	225	50	R	17	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	BONNET/CENTER/LEFT	OTHER DAMAGES	POLIEREN
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT		SCRATCH WITH PAINT DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
0	0					
[x]	REAR BUMPER/SIDE/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE		+DEUK	
			Repair paint - LI	New paint - E	Depr.	Total
3	0	LU =0.00 EUR	0 EUR		50 %	
			Repair paint - LI	New paint - E	Depr.	Total
3	15	LU =72.00 EUR	0 EUR	282.96 EUR	50 %	354.96 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
2	0	LU =0.00 EUR	369.84 EUR		50 %	369.84 EUR
[x]	REAR DOOR/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
4	0	LU =0.00 EUR	382.02 EUR		50 %	382.02 EUR
[x]	REAR DOOR/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
2	0	LU =0.00 EUR	382.02 EUR		50 %	382.02 EUR
[x]	WINDSCREEN/CENTER/RIGHT		WINDOW DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR

Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE BROKEN / CRACKED

	Repair paint - LI	New paint - E	Depr.	Total
7 0 LU =0.00 EUR	0 EUR		50 %	

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
6	I 4	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	58.32 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	REAR BUMPER	411.84 EUR	50 %	411.84 EUR

Number	Code	Description	Unit price	Depr.	Total
7	1	MIRROR GLASS	21.60 EUR	50 %	21.60 EUR

1	2	3	4	5	6	7	8	9	10
285.00	751.86	766.80	382.02	58.80	58.32	21.60	0	0	0
285.00	375.93	383.40	191.01	58.80	58.32	10.80	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
402.12	1922.28	0	2324.40
HOG: 0	BG: 2		NA Deprec. 1363.26
			0.00%
			TOTAL 1363.26

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 10/04/2017 Hour : 11:59 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	