

ARRD1W

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	58830 KM
File nr. :	1386543	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EVN495 / WDC1660041A175203 /		yr of constructionr :	/
E-File nr. :		First registration :	01/04/2013
VFS-nr. :		Color :	
Make + Model :	MERCEDES / ML	Fuel type :	DIESEL
Object nr. :	46163	Fuel :	
Classification :		Environment Class:	EURO 6
Customer company :	ANSELL HEALTHCARE EUROPE SA	Co2:	158g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	ML 250 BlueTEC 204PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	2143
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	204	kW:	150
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK	Service manual :	NOK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
First aid kit :		Oil level :	OK	[x]
Jack, wheelspanner :		Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :			
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :		
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :			
Wheel RES:	[x]	ANDERE	Tyre :	OK	[x]	>6 /	Rim :		/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	235	65	R	17	WINTER H
Rear tyre	235	65	R	17	WINTER H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/CENTER	DENT
[x]	BONNET/CENTER/RIGHT	CHIPS
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT BUMPER/CENTER/LEFT	HOLE/CRACK/TORN	CHROOM SIERLIJST VOORBUMPER	
	Repair paint - LI	New paint - E	Depr.	Total
1	20 LU =96.00 EUR	0 EUR	50 %	96.00 EUR

Others

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	CHROOM DEEL VOOR BUMPER	300.00 EUR	50 %	300.00 EUR

1	2	3	4	5	6	7	8	9	10
396.00	190.00	0	0	0	0	0	0	0	0
198.00	190.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
190.00	396.00	0	586.00
HOG: 0	BG: 2		NA Deprec. 388.00
			0.00%
			TOTAL 388.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/04/2017 Hour : 14:59 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	