

AQ10G0

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	138535 KM
File nr. :	1385178	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
368AKT / WDD2193221A137112 /		yr of constructionr :	/
E-File nr. :		First registration :	02/04/2009
VFS-nr. :		Color :	BLACK
Make + Model :	MERCEDES / CLS	Fuel type :	DIESEL
Object nr. :	69097	Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	IMCORP USA	Co2:	200g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	CLS 320CDI 211PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	2987
Gear box :	Automaat algemeen	Number of places:	4
Number of gears:		Number of doors:	4
HP:	211	kW:	155
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]	
Cert. of reg. / Part 1:		Cert. of conformity :	OK		
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :		Transport licence :			
Tax certificate :		Navigation CD/SD/DVD			
Fuel card :		Car radio :	OK	[x]	
Mobile phone kit :		Extinguisher :	OK	[x]	
		Warning triangle :	OK	[x]	
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	245	40	R	18	Y
Rear tyre	245	40	R	18	Y

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR
[x]	FRONT MUDGUARD/RIGHT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
1	25 LU =120.00 EUR	264.21 EUR		50 %	384.21 EUR
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH (WITHOUT PAINT DAMAGE)			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	BROKEN / CRACKED			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	0 EUR		50 %	

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FENDER FR	207.36 EUR	50 %	207.36 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	MIRROR	144.00 EUR	50 %	144.00 EUR

1	2	3	4	5	6	7	8	9	10
845.73	254.16	144.00	380.00	0	0	0	0	0	0
422.86	127.08	72.00	380.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
380.00	1243.89	0	1623.89
HOG: 0	BG: 2		NA Deprec. 1001.94
			0.00%
			TOTAL 1001.94

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 10/04/2017 Hour : 15:07 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	