

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	204883 KM
File nr. :	1384420	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GJE584 / WDD2122051A973098 /		yr of constructionr :	/
E-File nr. :		First registration :	21/02/2014
VFS-nr. :		Color :	GREY
Make + Model :	MERCEDES / E BREAK	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :	L	Environment Class:	EURO 5
Customer company :	EDF LUMINUS	Co2:	138g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	E200CDI	Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	2143
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:	EURO 5B		

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	NOK		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :		
Wheel RL :	[x]	KLÉBER	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :		
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RR :	[x]	KLÉBER	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :		
Wheel RES:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :			/	Hubcap :		

	[x]	Width	Height	Type	Rim	Index
Front tyre		245	45	R	17	WINTER V
Rear tyre		245	45	R	17	WINTER V

Remark : JNTES OXYDEES

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR BUMPER/CENTER/LEFT	DENT	
[x]	REAR DOOR/LEFT/FRONT	DENT	
[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	IN
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	POIGNEE
[x]	FRONT BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	+SOUS BASSEMENT
[x]	ROOF/CENTER/LEFT	DENT	RENFORT

Interior

[x]	SEAT FR	CUT / TORN
[x]	DOOR IN FL	SCRATCHED

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH (WITHOUT PAINT DAMAGE)
-----	------------------------------	--------------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	BONNET/CENTER/LEFT	DENT
-----	--------------------	------

	Repair paint - LI	New paint - E	Depr.	Total
1 30 LU =144.00 EUR	348.09 EUR		50 %	492.09 EUR

1	2	3	4	5	6	7	8	9	10
492.09	0	0	0	0	0	0	0	0	0
246.04	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	492.09	0	492.09
HOG: 0	BG: 2		NA Deprec. 246.04
			0.00%
			TOTAL 246.04

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

<p>Authorized by customer :</p> <p>Remark authorized customer : degats capot declare. KBC a refuse d'effectuer la reparation de la voiture. apres inspection seul le montant de 246,04€</p> <p>Date : 03/04/2017 Hour : 16:14</p> <p>Company :</p> <p>Executed by VAB Fleet Services</p> <p>E-Mail : @</p>	<p>Executed by VAB Fleet Services</p>
<p>Signature authorized by customer</p> 	