

AOWKTX

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	160199 KM
File nr. :	1384297	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ETO032 / WVWZZZAUZDW095867 /		yr of constructionr :	2013 / 00
E-File nr. :		First registration :	18/03/2013
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	57534	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	MISSION WALLONNE DES SECTEURS VERTS ASBL	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	GOLF BER Trendline 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	3
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :		
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4 /	Rim :	/	Hubcap :	
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	WINTER H
Rear tyre	195	65	R	15	WINTER H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	DENT		
		Repair paint - LI	New paint - E	Depr.
				Total
4	0 LU =0.00 EUR	211.80 EUR		50 %
				211.80 EUR
[x]	REAR MUDGUARD/LEFT/CENTER	DENT		
		Repair paint - LI	New paint - E	Depr.
				Total
3	0 LU =0.00 EUR	308.20 EUR		50 %
				308.20 EUR
[x]	FRONT DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
				Total
2	0 LU =0.00 EUR	318.35 EUR		50 %
				318.35 EUR
[x]	FRONT MUDGUARD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	DEUK	
		Repair paint - LI	New paint - E	Depr.
				Total
2	0 LU =0.00 EUR	220.18 EUR		50 %
				220.18 EUR
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE	+LINKS	
		Repair paint - LI	New paint - E	Depr.
				Total
1	0 LU =0.00 EUR	211.80 EUR		50 %
				211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	538.53	308.20	211.80	0	0	0	0	0	0
105.90	269.26	154.10	105.90	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	1270.33	0	1270.33
HOG: 0	BG: 0		NA Deprec. 635.16
			0.00%
			TOTAL 635.16

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 03/04/2017 Hour : 11:33 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	