

AI6IR5

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	61594 KM
File nr. :	1378993	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CRZ359 / VF38ERHDABL109272 /		yr of constructionr :	/
E-File nr. :		First registration :	14/02/2012
VFS-nr. :		Color :	GREY
Make + Model :	PEUGEOT / 508 BREAK	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SOA PEOPLE SA	Co2:	150g/km
Driver :		Remote controls:	2
Covering :	TISSUE-LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	508 SW Allure 136PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1997
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:	14/02/2018	Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :	OK	[x]	Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]	MICHELIN	Tyre :	OK	[x]	>6 /	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	17	WINTER H
Rear tyre	215	55	R	17	WINTER V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/LEFT/FRONT	DENT	
[x]	ROOF STYLE/REAR/LEFT	DENT	
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	BORD PORTE
[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	IN
[x]	REAR DOOR/RIGHT/FRONT	DENT	
[x]	FRONT THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	IN
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	BORD DE PORTE
[x]	FRONT DOOR/RIGHT/REAR	CHIPS	POIGNEE
[x]	FRONT DOOR/RIGHT/FRONT	DENT	2X
[x]	FRONT MUDGUARD/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	G/D
[x]	FRONT/RIGHT	HOLE/CRACK/TORN	MOULURE CHROME
[x]	FRONT BUMPER/RIGHT/CORNER	SCRATCH (WITHOUT PAINT DAMAGE)	

Interior

[x]	SEAT FL	CARVED
[x]	DOOR IN REAR L	SCRATCHED
[x]	BOOT LID IN	SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/REAR	DENT
-----	-------------------------	------

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	0	0	0	0	0	0	0	0	0
63.00	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	0	0	63.00
HOG: 0	BG: 0		NA Deprec. 63.00
			0.00%
			TOTAL 63.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/04/2017 Hour : 10:19 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	