

ATOIBY

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	181248 KM
File nr. :	1387453	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CIH136 / WVWZZZ3CZCE103308 /		yr of constructionr :	/
E-File nr. :		First registration :	05/12/2011
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / PASSAT	Fuel type :	DIESEL
Object nr. :	10785	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	DANONE NV	Co2:	116g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	PASSAT VAR Comfortline 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK
Jack, wheelspanner :	OK	[x]	Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	WINTER H
Rear tyre	215	55	R	16	WINTER H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/FRONT	DENT		
[x]	REAR DOOR/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	POLIEREN	
[x]	REAR DOOR/RIGHT/FRONT	DENT		

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT DOOR/LEFT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT DOOR/RIGHT/REAR	DENT		+KRASSEN	
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT THRESHOLD/RIGHT/FRONT	HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total
2	40 LU =192.00 EUR	0 EUR	414.00 EUR	50 %	606.00 EUR

Others

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1 DOORSTEP		250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
318.35	856.00	190.00	318.35	0	0	0	0	0	0
159.18	428.00	190.00	159.18	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
190.00	1492.70	0	1682.70
HOG: 0	BG: 0		NA Deprec. 936.35
			0.00%
			TOTAL 936.35

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/04/2017 Hour : 13:27 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	