

ANZGLB

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	124931 KM
File nr. :	1383523	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EPJ381 / VF34E9HP0DS020114 /		yr of constructionr :	2013 / 00
E-File nr. :		First registration :	14/02/2013
VFS-nr. :		Color :	BLUE
Make + Model :	PEUGEOT / 308 BREAK	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	WURTH BELUX NV	Co2:	119g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	308 SW Access 92PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	92	kW:	68
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK			Service manual :	OK	[x]
Cert. of reg. / Part 1:				Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]		Insurance certificate :		
Warning vest :				Transport licence :		
Tax certificate :				Navigation CD/SD/DVD		
Fuel card :				Car radio :	OK	[x]
Mobile phone kit :				Extinguisher :	OK	[x]
				Warning triangle :	OK	[x]
First aid kit :	OK	[x]		Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	4-6 /	Rim :		Hubcap :	
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	>6 /	Rim :		Hubcap :	
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	4-6 /	Rim :		Hubcap : [x] SCRATCHED
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	>6 /	Rim :		Hubcap :	[x] SCRATCHED
Wheel RES:	[x]		Tyre :	OK	[x]	>6 /	Rim :		Hubcap :	

	[x]	Width	Height	Type	Rim	Index
Front tyre		195	65	R	15	WINTER T
Rear tyre		195	65	R	15	WINTER T

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/CENTER/RIGHT			SCRATCH WITH PAINT DAMAGE		
			Repair paint - LI	New paint - E	Depr.	Total
1	0	LU =0.00 EUR	301.68 EUR		50 %	301.68 EUR
[x]	ROOF/CENTER/RIGHT			DENT		2
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR

Interior

[x]	SEAT REAR L			SCRATCHED		
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-intvlr-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER)	64.32 EUR		64.32 EUR

Others

HUB CAP REAR RIGHT

			Repair paint - LI	New paint - E	Depr.	Total
3	0	LU =0.00 EUR			50 %	

Pieces

	Number	Code	Description	Unit price	Depr.	Total
3	1	WHEEL CAP		30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
301.68	82.80	30.00	64.32	0	0	0	0	0	0
150.84	82.80	15.00	64.32	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
147.12	331.68	0	478.80
HOG: 0	BG: 0		NA Deprec. 312.96
			0.00%
			TOTAL 312.96

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : LAATSTE BESTUURDER/ WAREN REEDS SCHADES EN WAGEN WAS VUIL BIJ OVERDRACHT/WIL NIET ONDERTEKENEN Date : 04/04/2017 Hour : 12:31 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	