

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	100087 KM
File nr. :	1387090	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ESB992 / WDD2042011G077062 /		yr of constructionr :	/
E-File nr. :		First registration :	06/03/2013
VFS-nr. :		Color :	GREY
Make + Model :	MERCEDES / C BREAK	Fuel type :	DIESEL
Object nr. :	42512	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CYBERTRUST BELGIUM NV	Co2:	133g/km
Driver :		Remote controls:	2
Covering :	TISSUE-LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	C BRE 200 CDI BlueEFF. S&S 136PK	Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	2143
Gear box :	6-speed manual gearbox	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :			/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]	ANDERE	Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	45	R	17	WINTER V
Rear tyre	225	45	R	17	WINTER V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

Interior

[x] SEAT FL CUT / TORN

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x] REAR MUDGUARD/LEFT/REAR SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

[x] REAR MUDGUARD/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

[x] REAR DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] BONNET/CENTER/LEFT OTHER DAMAGES CHEMISCHE VLEKKEN

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR

[x] FRONT BUMPER/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Interior

[x] DOOR IN FL CUT / TORN

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-intdash-01	PLASTICS REPAIR INTERIRO	110.64 EUR		110.64 EUR

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE		SCRATCH WITH PAINT DAMAGE		
Number	Code	Description	Unit price	Depr.	Total
8	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR	110.64 EUR
[x]	OUTSIDE MIRROR RIGHTHAND SIDE		BROKEN / CRACKED		
		Repair paint - LI	New paint - E	Depr.	Total
8	0	LU =0.00 EUR	0 EUR	50 %	

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
9	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
9	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
9	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
8	1	INDICATOR	150.00 EUR	50 %	150.00 EUR

1	2	3	4	5	6	7	8	9	10
322.44	290.08	308.20	211.80	308.20	318.35	318.35	260.64	285.00	0
216.54	145.04	154.10	105.90	154.10	159.18	159.18	185.64	285.00	0

INNOVATIVE	TRADITIONAL	GENERAL	
506.28	2116.78	0	2623.06
HOG: 0	BG: 0		NA Deprec. 1564.67
			0.00%
			TOTAL 1564.67

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/04/2017 Hour : 11:41 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	