

ARSZCY

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	156518 KM
File nr. :	1386578	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CDE207 / YV1DZ88A1C2267902 /		yr of constructionr :	/
E-File nr. :		First registration :	25/10/2011
VFS-nr. :		Color :	GREY
Make + Model :	VOLVO / XC60	Fuel type :	DIESEL
Object nr. :	5017	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	INBEV BELGIUM SA	Co2:	149g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	XC60 DRIVe Kinetic St/St 163PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	1984
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	2-4 /	Rim :	[x] WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	235	65	R	17	H
Rear tyre	235	65	R	17	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Interior

[x] SEAT FR DIRTY

Number	Code	Description	Unit price	Depr.	Total
2	I 1	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	14.58 EUR

Others

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
95.00	14.58	0	0	0	0	0	0	0	0
95.00	14.58	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
109.58	0	0	109.58
HOG: 0	BG: 0		NA Deprec. 109.58
			0.00%
			TOTAL 109.58

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/04/2017 Hour : 09:34 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	