

ASOT8X

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	153688 KM
File nr. :	1387219	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EXB457 / W0LPD8EW1D8046649 /		yr of constructionr :	/
E-File nr. :		First registration :	11/04/2013
VFS-nr. :		Color :	WHITE
Make + Model :	OPEL / ASTRA BREAK	Fuel type :	DIESEL
Object nr. :	69243	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CEGELEC CONTROL SYSTEMS & SERVICES	Co2:	105g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	ASTRA BRE ecoFL.Enjoy Active St/St 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1686
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	2-4 /	Rim :		/
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	H
Rear tyre	225	50	R	17	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/RIGHT/REAR DENT

Interior

[x] ARM REST SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] WINDSCREEN/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	0 EUR		50 %	
	Repair paint - LI	New paint - E	Depr.	Total
1 25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

[x] FRONT MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE +DEUK

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

[x] FRONT BUMPER/RIGHT/SIDE SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE BROKEN / CRACKED

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	0 EUR		50 %	
	Repair paint - LI	New paint - E	Depr.	Total
3 10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	MIRROR	120.00 EUR	50 %	120.00 EUR

1	2	3	4	5	6	7	8	9	10
487.20	220.18	168.00	211.80	0	0	0	0	0	0
243.60	110.09	84.00	105.90	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	1087.18	0	1087.18
HOG: 0	BG: 0		NA Deprec. 543.59
			0.00%
			TOTAL 543.59

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 11/04/2017 Hour : 13:38 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	