

☒ EFFECTIVE    ☐ NOT EXECUTED    ☒ COLLECTION    ☐ DELIVERY

[x] = Status Modification

|                               |                                       |                          |                               |
|-------------------------------|---------------------------------------|--------------------------|-------------------------------|
| Commissionar :                | KBC REMARKETING                       | Cleanliness :            | INT: CLEAN [x] EXT: DIRTY [x] |
| Owner :                       |                                       | Mileage :                | 105738 KM                     |
| File nr. :                    | 1387320                               | Mileage start / arrival: | 0 / 0                         |
| Reg number / Chassis / Ref :  |                                       | Mileag ref. service :    | 0                             |
| 1EWN483 / W0LPE9EM7D2067364 / |                                       | yr of constructionr :    | 2013 / 00                     |
| E-File nr. :                  |                                       | First registration :     | 08/04/2013                    |
| VFS-nr. :                     |                                       | Color :                  | BLACK                         |
| Make + Model :                | OPEL / ZAFIRA TOURER                  | Fuel type :              | DIESEL                        |
| Object nr. :                  | 66793                                 | Fuel :                   |                               |
| Classification :              | N                                     | Environment Class:       | EURO 5                        |
| Customer company :            | EURO POOL SYSTEMS BENELUX BVBA        | Co2:                     | 119g/km                       |
| Driver :                      |                                       | Remote controls:         | 2                             |
| Covering :                    | TISSUE                                | Number keys :            | 2 [x]                         |
| Vehicle kind :                |                                       | Seats (minivan) :        | 5 [x]                         |
| Vehicle type :                | ZAFIRA TOURER ecoFL.Cosmo St/St.130PK | Country registration :   | BELGIUM                       |

|                              |            |                     |         |
|------------------------------|------------|---------------------|---------|
| VAT over the margin - car:   | No         | Metallic paint:     | Yes     |
| Variant car:                 | MONOVOLUME | Engine size:        | 1956    |
| Gear box :                   | Manueel    | Number of places:   | 5       |
| Number of gears:             | 6          | Number of doors:    | 5       |
| HP:                          | 131        | kW:                 | 96      |
| Fisc HP                      |            | Imported vehicle:   |         |
| Animals transported:         |            | Smoked in vehicle:  |         |
| Due date vehicle inspection: |            | Extra set of tires: |         |
|                              |            | Use:                | Unknown |
| General condition:           |            |                     |         |

|                                     |                           |
|-------------------------------------|---------------------------|
| Original registr. number : OK       | Service manual :          |
| Cert. of reg. / Part 1:             | Cert. of conformity : OK  |
| Cert. of reg. copy / Part 2: OK [x] | Insurance certificate :   |
| Warning vest :                      | Transport licence :       |
| Tax certificate :                   | Navigation CD/SD/DVD      |
| Fuel card :                         | Car radio : OK [x]        |
| Mobile phone kit :                  | Extinguisher : OK [x]     |
|                                     | Warning triangle : OK [x] |
| First aid kit : OK [x]              | Oil level : OK [x]        |
| Jack, wheelspanner : [x]            | Filled up : 0             |

## Wheels and tyres:

|            |        |    |   |       |   |          |
|------------|--------|----|---|-------|---|----------|
| Wheel FL:  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | Tyre : | OK | / | Rim : | / | Hubcap : |

|            | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      |      | 0   |       |
| Rear tyre  | 0     | 0      |      | 0   |       |

Remark :

## Wheels and tyres:

|            |        |    |   |       |   |          |
|------------|--------|----|---|-------|---|----------|
| Wheel FL:  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | Tyre : | OK | / | Rim : | / | Hubcap : |

|            | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      |      | 0   |       |
| Rear tyre  | 0     | 0      |      | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork & windows

|     |                            |                                |               |
|-----|----------------------------|--------------------------------|---------------|
| [x] | REAR MUDGUARD/RIGHT/CENTER | SCRATCH WITH PAINT DAMAGE      |               |
| [x] | REAR DOOR/RIGHT/REAR       | SCRATCH WITH PAINT DAMAGE      | BINNENKANT    |
| [x] | FRONT DOOR/RIGHT/REAR      | SCRATCH WITH PAINT DAMAGE      | BINNENKANT    |
| [x] | FRONT DOOR/RIGHT/FRONT     | DENT                           | MET LAKSCHADE |
| [x] | FRONT MUDGUARD/LEFT/REAR   | SCRATCH WITH PAINT DAMAGE      |               |
| [x] | BONNET/CENTER/RIGHT        | SCRATCH (WITHOUT PAINT DAMAGE) |               |
| [x] | FRONT MUDGUARD/RIGHT/REAR  | SCRATCH WITH PAINT DAMAGE      |               |

## STATUS: NOT ACCEPTABLE

### Bodywork & windows

|     |                           |                           |                     |            |
|-----|---------------------------|---------------------------|---------------------|------------|
| [x] | REAR DOOR/CENTER/LEFT     | SCRATCH WITH PAINT DAMAGE | +DEUK MET LAKSCHADE |            |
|     |                           | Repair paint - LI         | New paint - E       | Depr.      |
|     |                           |                           |                     | Total      |
| 4   | 0 LU =0.00 EUR            | 301.68 EUR                |                     | 50 %       |
|     |                           |                           |                     | 301.68 EUR |
| [x] | REAR BUMPER/RIGHT/CORNER  | SCRATCH WITH PAINT DAMAGE |                     |            |
|     |                           | Repair paint - LI         | New paint - E       | Depr.      |
|     |                           |                           |                     | Total      |
| 3   | 0 LU =0.00 EUR            | 211.80 EUR                |                     | 50 %       |
|     |                           |                           |                     | 211.80 EUR |
| [x] | REAR MUDGUARD/LEFT/FRONT  | SCRATCH WITH PAINT DAMAGE |                     |            |
|     |                           | Repair paint - LI         | New paint - E       | Depr.      |
|     |                           |                           |                     | Total      |
| 2   | 0 LU =0.00 EUR            | 308.20 EUR                |                     | 50 %       |
|     |                           |                           |                     | 308.20 EUR |
| [x] | REAR DOOR/LEFT/FRONT      | SCRATCH WITH PAINT DAMAGE |                     |            |
|     |                           | Repair paint - LI         | New paint - E       | Depr.      |
|     |                           |                           |                     | Total      |
| 2   | 0 LU =0.00 EUR            | 318.35 EUR                |                     | 50 %       |
|     |                           |                           |                     | 318.35 EUR |
| [x] | REAR DOOR/RIGHT/CENTER    | SCRATCH WITH PAINT DAMAGE |                     |            |
|     |                           | Repair paint - LI         | New paint - E       | Depr.      |
|     |                           |                           |                     | Total      |
| 5   | 0 LU =0.00 EUR            | 318.35 EUR                |                     | 50 %       |
|     |                           |                           |                     | 318.35 EUR |
| [x] | REAR THRESHOLD/RIGHT/REAR | DENT                      |                     |            |
|     |                           | Repair paint - LI         | New paint - E       | Depr.      |
|     |                           |                           |                     | Total      |
| 5   | 40 LU =192.00 EUR         | 0 EUR                     | 414.00 EUR          | 50 %       |
|     |                           |                           |                     | 606.00 EUR |

[x] FRONT DOOR/LEFT/CENTER

SCRATCH WITH PAINT DAMAGE

|                  | Repair paint - LI | New paint - E | Depr. | Total      |
|------------------|-------------------|---------------|-------|------------|
| 2 0 LU =0.00 EUR | 318.35 EUR        |               | 50 %  | 318.35 EUR |

[x] FRONT BUMPER/LEFT/SIDE

SCRATCH WITH PAINT DAMAGE

|                  | Repair paint - LI | New paint - E | Depr. | Total      |
|------------------|-------------------|---------------|-------|------------|
| 1 0 LU =0.00 EUR | 211.80 EUR        |               | 50 %  | 211.80 EUR |

## Pieces

| Number | Code | Description | Unit price | Depr. | Total      |
|--------|------|-------------|------------|-------|------------|
| 1      | 1    | SPOILER     | 70.00 EUR  | 50 %  | 70.00 EUR  |
| Number | Code | Description | Unit price | Depr. | Total      |
| 5      | 1    | DOORSTEP    | 250.00 EUR | 50 %  | 250.00 EUR |

| 1      | 2      | 3      | 4      | 5       | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|--------|---------|---|---|---|---|----|
| 281.80 | 944.90 | 211.80 | 301.68 | 1174.35 | 0 | 0 | 0 | 0 | 0  |
| 140.90 | 472.45 | 105.90 | 150.84 | 587.18  | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                    |
|------------|-------------|---------|--------------------|
| 0          | 2914.53     | 0       | 2914.53            |
| HOG: 0     | BG: 0       |         | NA Deprec. 1457.26 |
|            |             |         | 0.00%              |
|            |             |         | TOTAL 1457.26      |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|                               |                                  |                                 |
|-------------------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min            | Waiting time : 0 min<br>Reason : | Towing time : 0 min<br>Reason : |
| NOT EXECUTED : No<br>Reason : |                                  |                                 |
| Remark :                      |                                  |                                 |

## Prices in EUR without VAT

|                                                                                                                                                                      |                                |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|
| Authorized by customer :<br><br>Remark authorized customer :<br><br>Date : 11/04/2017      Hour : 16:57<br>Company :<br>Executed by VAB Fleet Services<br>E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br>                                              |                                |