

AMF585

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	74571 KM
File nr. :	1382289	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ETJ001 / VF1JZ1UB248756470 /		yr of constructionr :	2013 / 00
E-File nr. :		First registration :	15/03/2013
VFS-nr. :		Color :	RED
Make + Model :	RENAULT / GRAND SCENIC	Fuel type :	PETROL
Object nr. :	12556	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	NCI SA	Co2:	178g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	7 [x]
Vehicle type :	GR.SCENIC Expression 7pl.110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1598
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
		Warning triangle :	OK [x]
First aid kit :	OK [x]	Oil level :	OK [x]
Jack, wheelspanner :		Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :		
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :		
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6 /	Rim :		/	Hubcap :	[x] SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :	[x] SCRATCHED	
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	WINTER H
Rear tyre	205	60	R	16	WINTER H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR DOOR/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	MEERDERE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	MEERDERE
[x]	FRONT DOOR/RIGHT/CENTER	DENT	
[x]	BONNET/RIGHT/CENTER	DENT	+KRASSEN
[x]	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	MEERDERE	
		Repair paint - LI	New paint - E	Depr.
1	0 LU =0.00 EUR	211.80 EUR		50 %
				211.80 EUR
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
2	0 LU =0.00 EUR	318.35 EUR		50 %
				318.35 EUR

Others

	HUB CAP FR			
		Repair paint - LI	New paint - E	Depr.
3	0 LU =0.00 EUR			50 %

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	318.35	30.00	0	0	0	0	0	0	0
105.90	159.18	15.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	560.15	0	560.15
HOG: 0	BG: 0		NA Deprec. 280.08
			0.00%
			TOTAL 280.08

APPRAISAL

www.vabfleetservices.be

Date : 30/03/2017

5/5

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min 	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 30/03/2017 Hour : 11:51	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	