

AR83BI

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	180254 KM
File nr. :	1386132	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FLI770 / VF3WE9HP0DE029715 /		yr of constructionr :	/
E-File nr. :		First registration :	06/08/2013
VFS-nr. :		Color :	GREY
Make + Model :	PEUGEOT / 207 BREAK	Fuel type :	DIESEL
Object nr. :	71053	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ASWEBO NV	Co2:	110g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	207 SW Active FAP 92PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	92	kW:	68
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6 /	Rim :	/ Hubcap : [x] SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	/ Hubcap : [x] SCRATCHED	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/ Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	185	65	R	15	T
Rear tyre	185	65	R	15	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/LEFT/REAR	DENT

Interior

[x]	BOOT LID IN	CUT / TORN
-----	-------------	------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/CORNER	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
				Total
5	0 LU =0.00 EUR	169.44 EUR		50 %
				169.44 EUR
[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	MEERDERE	
		Repair paint - LI	New paint - E	Depr.
				Total
3	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR	
				110.64 EUR
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	MEERDERE	
		Repair paint - LI	New paint - E	Depr.
				Total
2	0 LU =0.00 EUR	246.56 EUR		50 %
				246.56 EUR
[x]	THRESHOLD FRONT/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
				Total
6	0 LU =0.00 EUR	248.40 EUR		50 %
				248.40 EUR
[x]	FRONT BUMPER/LEFT/CORNER	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
				Total
4	0 LU =0.00 EUR	169.44 EUR		50 %
				169.44 EUR

Interior

[x]	SEAT REAR RIGHT	DIRTY		
		Repair paint - LI	New paint - E	Depr.
				Total
7	I 1 specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	
				14.58 EUR

Others

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

1	2	3	4	5	6	7	8	9	10
48.00	246.56	110.64	169.44	169.44	248.40	14.58	0	0	0
24.00	123.28	110.64	84.72	84.72	124.20	14.58	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
125.22	881.84	0	1007.06
HOG: 0	BG: 1		NA Deprec. 566.14
			0.00%
			TOTAL 566.14

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/04/2017 Hour : 14:45 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	