

ARS7T8

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	83617 KM
File nr. :	1386560	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EQM980 / W0LPF6EWXDG064622 /		yr of constructionr :	2013 / 00
E-File nr. :		First registration :	23/02/2013
VFS-nr. :		Color :	BLACK
Make + Model :	OPEL / ASTRA	Fuel type :	DIESEL
Object nr. :	12217	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	I.B.A. SA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	ASTRA BER ecoFLEX Sport St/St 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1686
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
	Warning triangle : OK [x]
First aid kit : OK [x]	Oil level : OK [x]
Jack, wheelspanner :	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	2-4 /	Rim :	/
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	M+S
Rear tyre	225	50	R	17	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/FRONT	DENT
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	ROOF/REAR/LEFT			OTHER DAMAGES		INWERKING	
	Repair paint - LI			New paint - E		Depr.	Total
2	0 LU =0.00 EUR			481.50 EUR		50 %	481.50 EUR
[x]	FRONT DOOR/LEFT/FRONT			DENT			
	Number	Code	Description	Unit price	Depr.	Total	
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR	
[x]	BONNET/CENTER/RIGHT			OTHER DAMAGES		HOES	
	Repair paint - LI			New paint - E		Depr.	Total
4	0 LU =0.00 EUR			0 EUR		50 %	

Interior

[x]	CENTER CONSOLE	HOLE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	0 EUR		50 %	

Pieces

	Number	Code	Description	Unit price	Depr.	Total
3	1	HOES HANDREM		60.00 EUR	50 %	60.00 EUR
	Number	Code	Description	Unit price	Depr.	Total
4	1	HOES		50.00 EUR	50 %	50.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	481.50	60.00	50.00	0	0	0	0	0	0
63.00	240.75	30.00	25.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	591.50	0	654.50
HOG: 0	BG: 0		NA Deprec. 358.75
			0.00%
			TOTAL 358.75

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/04/2017 Hour : 09:50 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	