

ATCYEZ

☒ EFFECTIVE ☐ NOT EXECUTED ☐ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	183526 KM
File nr. :	1387710	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
YRM894 / VF1KCTEEF39955265 /		yr of constructionr :	/
E-File nr. :		First registration :	11/07/2008
VFS-nr. :		Color :	WHITE
Make + Model :	RENAULT / KANGOO	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	ONBEKEND	Co2:	147g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:		Engine size:	1461
Gear box :		Number of places:	
Number of gears:		Number of doors:	
HP:	68	kW:	50
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	[x]
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
		Warning triangle :	OK [x]
First aid kit :	OK [x]	Oil level :	OK [x]
Jack, wheelspanner :	OK [x]	Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK [x]	2-4 /	Rim :	/	Hubcap :	[x]	BROKEN / CRACKED	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK [x]	2-4 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK [x]	2-4 /	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK [x]	2-4 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	175	65	R	14	T
Rear tyre	175	65	R	14	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE	HERSTELD
[x]	BONNET/CENTER/RIGHT/FRONT	DENT	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	HOLE/CRACK/TORN			
Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

Accessories and others

[x]	VEH COVERED WITH STICKERS	STICKER(S)			
Number	Code	Description	Unit price	Depr.	Total
0	0				

Others

	HUB CAP REAR L				
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR			50 %	
	HUB CAP FR				
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	BACK WINDOW	187.50 EUR	50 %	187.50 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

1	2	3	4	5	6	7	8	9	10
0	110.64	307.50	45.00	0	0	0	0	0	0
0	110.64	153.75	22.50	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
110.64	352.50	0	463.14
HOG: 0	BG: 3		NA Deprec. 286.89
			0.00%
			TOTAL 286.89

APPRAISAL

www.vabfleetservices.be

Date : 06/04/2017

5/5

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min 	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 06/04/2017 Hour : 14:11	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	