

☒ EFFECTIVE    ☐ NOT EXECUTED    ☒ COLLECTION    ☐ DELIVERY

[x] = Status Modification

|                               |                                |                          |                               |
|-------------------------------|--------------------------------|--------------------------|-------------------------------|
| Commissionar :                | KBC REMARKETING                | Cleanliness :            | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner :                       |                                | Mileage :                | 155244 KM                     |
| File nr. :                    | 1387209                        | Mileage start / arrival: | 0 / 0                         |
| Reg number / Chassis / Ref :  |                                | Mileag ref. service :    | 0                             |
| 1ETM747 / VF1KZ140648660828 / |                                | yr of constructionr :    | /                             |
| E-File nr. :                  |                                | First registration :     | 18/03/2013                    |
| VFS-nr. :                     |                                | Color :                  | BLACK                         |
| Make + Model :                | RENAULT / MEGANE               | Fuel type :              | DIESEL                        |
| Object nr. :                  | 50468                          | Fuel :                   |                               |
| Classification :              |                                | Environment Class:       | EURO 5                        |
| Customer company :            | EGEMIN NV                      | Co2:                     | 90g/km                        |
| Driver :                      |                                | Remote controls:         | 1                             |
| Covering :                    | TISSUE                         | Number keys :            | 1 [x]                         |
| Vehicle kind :                | VEHICLE                        | Seats (minivan) :        | 0                             |
| Vehicle type :                | MEGANE GT Energy Bose Ed.110PK | Country registration :   | BELGIUM                       |

|                              |         |                     |         |
|------------------------------|---------|---------------------|---------|
| VAT over the margin - car:   | No      | Metallic paint:     | Yes     |
| Variant car:                 | BREAK   | Engine size:        | 1461    |
| Gear box :                   | Manueel | Number of places:   | 5       |
| Number of gears:             | 6       | Number of doors:    | 5       |
| HP:                          | 110     | kW:                 | 81      |
| Fisc HP                      |         | Imported vehicle:   |         |
| Animals transported:         | No      | Smoked in vehicle:  | No      |
| Due date vehicle inspection: |         | Extra set of tires: | No      |
|                              |         | Use:                | Unknown |

|                    |
|--------------------|
| General condition: |
|--------------------|

|                                     |    |     |  |                                |    |     |  |
|-------------------------------------|----|-----|--|--------------------------------|----|-----|--|
| <b>Original registr. number :</b>   | OK |     |  | <b>Service manual :</b>        |    | [x] |  |
| <b>Cert. of reg. / Part 1:</b>      |    |     |  | <b>Cert. of conformity :</b>   | OK |     |  |
| <b>Cert. of reg. copy / Part 2:</b> | OK | [x] |  | <b>Insurance certificate :</b> |    |     |  |
| <b>Warning vest :</b>               | OK | [x] |  | <b>Transport licence :</b>     |    |     |  |
| <b>Tax certificate :</b>            |    |     |  | <b>Navigation CD/SD/DVD</b>    | OK | [x] |  |
| <b>Fuel card :</b>                  |    |     |  | <b>Car radio :</b>             | OK | [x] |  |
| <b>Mobile phone kit :</b>           |    |     |  | <b>Extinguisher :</b>          | OK | [x] |  |
|                                     |    |     |  | <b>Warning triangle :</b>      | OK | [x] |  |
| <b>First aid kit :</b>              | OK | [x] |  | <b>Oil level :</b>             | OK | [x] |  |
| <b>Jack, wheelspanner :</b>         | OK | [x] |  | <b>Filled up :</b>             | 0  |     |  |

## Wheels and tyres: Summer tires

|                   |     |          |               |     |     |       |              |              |                 |                 |                 |  |
|-------------------|-----|----------|---------------|-----|-----|-------|--------------|--------------|-----------------|-----------------|-----------------|--|
| <b>Wheel FL :</b> | [x] | KLÉBER   | <b>Tyre :</b> | OK  | [x] | 2-4 / | <b>Rim :</b> |              | /               | <b>Hubcap :</b> |                 |  |
| <b>Wheel RL :</b> | [x] | UNIROYAL | <b>Tyre :</b> | OK  | [x] | 2-4 / | <b>Rim :</b> | [x]          | WHEEL SCRATCHED | /               | <b>Hubcap :</b> |  |
| <b>Wheel FR :</b> | [x] | KLÉBER   | <b>Tyre :</b> | [x] | OK  | [x]   | 2-4 /        | <b>Rim :</b> |                 | /               | <b>Hubcap :</b> |  |
| <b>Wheel RR :</b> | [x] | UNIROYAL | <b>Tyre :</b> | OK  | [x] | 2-4 / | <b>Rim :</b> | [x]          | WHEEL SCRATCHED | /               | <b>Hubcap :</b> |  |
| <b>Wheel RES:</b> | [x] | MICHELIN | <b>Tyre :</b> | OK  | [x] | >6 /  | <b>Rim :</b> |              | /               | <b>Hubcap :</b> |                 |  |

|                   |     |              |               |             |            |              |
|-------------------|-----|--------------|---------------|-------------|------------|--------------|
|                   | [x] | <b>Width</b> | <b>Height</b> | <b>Type</b> | <b>Rim</b> | <b>Index</b> |
| <b>Front tyre</b> |     | 205          | 50            | R           | 17         | WINTER H     |
| <b>Rear tyre</b>  |     | 205          | 50            | R           | 17         | WINTER H     |

**Remark :**

### Wheels and tyres:

|            |        |    |   |       |   |          |
|------------|--------|----|---|-------|---|----------|
| Wheel FL:  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | Tyre : | OK | / | Rim : | / | Hubcap : |

|            |       |        |      |     |       |
|------------|-------|--------|------|-----|-------|
| [x]        | Width | Height | Type | Rim | Index |
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

|     |                         |                                |          |
|-----|-------------------------|--------------------------------|----------|
| [x] | REAR DOOR/CENTER/RIGHT  | SCRATCH WITH PAINT DAMAGE      |          |
| [x] | BONNET/CENTER/RIGHT     | SCRATCH (WITHOUT PAINT DAMAGE) | MEERDERE |
| [x] | FRONT BUMPER/RIGHT/SIDE | SCRATCH (WITHOUT PAINT DAMAGE) |          |

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

|     |                           |                           |               |            |
|-----|---------------------------|---------------------------|---------------|------------|
| [x] | REAR MUDGUARD/LEFT/CENTER | SCRATCH WITH PAINT DAMAGE | +DEURINSLAG   |            |
|     |                           | Repair paint - LI         | New paint - E | Depr.      |
| 3   | 0 LU =0.00 EUR            | 308.20 EUR                |               | 50 %       |
|     |                           |                           |               | 308.20 EUR |
| [x] | REAR MUDGUARD/RIGHT/FRONT | DENT                      |               |            |
|     |                           | Repair paint - LI         | New paint - E | Depr.      |
| 4   | 0 LU =0.00 EUR            | 308.20 EUR                |               | 50 %       |
|     |                           |                           |               | 308.20 EUR |
| [x] | REAR DOOR/LEFT/CENTER     | SCRATCH WITH PAINT DAMAGE |               |            |
|     |                           | Repair paint - LI         | New paint - E | Depr.      |
| 2   | 0 LU =0.00 EUR            | 318.35 EUR                |               | 50 %       |
|     |                           |                           |               | 318.35 EUR |

### Interior

|     |                      |                          |               |            |
|-----|----------------------|--------------------------|---------------|------------|
| [x] | DASHBORD             | SCRATCHED                |               |            |
|     |                      |                          |               |            |
|     | Number Code          | Description              | Unit price    | Depr.      |
| 1   | I 1 i-vab-intdash-01 | PLASTICS REPAIR INTERIRO | 110.64 EUR    |            |
|     |                      |                          |               | 110.64 EUR |
| [x] | SEAT FL              | CUT / TORN               |               |            |
|     |                      | Repair paint - LI        | New paint - E | Depr.      |
| 1   | 25 LU =120.00 EUR    | 0 EUR                    |               | 50 %       |
|     |                      |                          |               | 120.00 EUR |

### Others

RIM REAR LEFT

|   |                       |                    |            |       |           |
|---|-----------------------|--------------------|------------|-------|-----------|
|   | Number Code           | Description        | Unit price | Depr. | Total     |
| 5 | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR  |       | 95.00 EUR |

RIM REAR RIGHT

|   |                       |                    |            |       |           |
|---|-----------------------|--------------------|------------|-------|-----------|
|   | Number Code           | Description        | Unit price | Depr. | Total     |
| 5 | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR  |       | 95.00 EUR |

Pieces

| Number | Code | Description            | Unit price | Depr. | Total      |
|--------|------|------------------------|------------|-------|------------|
| 1      | 1    | SEAT UPHOLSTERY TISSUE | 120.00 EUR | 50 %  | 120.00 EUR |

| 1      | 2      | 3      | 4      | 5      | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|--------|--------|---|---|---|---|----|
| 350.64 | 318.35 | 308.20 | 308.20 | 190.00 | 0 | 0 | 0 | 0 | 0  |
| 230.64 | 159.18 | 154.10 | 154.10 | 190.00 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                   |
|------------|-------------|---------|-------------------|
| 300.64     | 1174.75     | 0       | 1475.39           |
| HOG: 0     | BG: 0       |         | NA Deprec. 888.02 |
|            |             |         | 0.00%             |
|            |             |         | TOTAL 888.02      |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

|                               |                                  |                                 |
|-------------------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min            | Waiting time : 0 min<br>Reason : | Towing time : 0 min<br>Reason : |
| NOT EXECUTED : No<br>Reason : |                                  |                                 |
| Remark :                      |                                  |                                 |

## Prices in EUR without VAT

|  |                                |
|--|--------------------------------|
| Authorized by customer :<br><br>Remark authorized customer :<br><br>Date : 10/04/2017      Hour : 09:23<br>Company :<br>Executed by VAB Fleet Services<br>E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br>  |                                |