

AUXGYC

☒ EFFECTIVE ☐ NOT EXECUTED ☐ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	146955 KM
File nr. :	1388893	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GFA140 / YV1DZ31A1F2696020 /		yr of constructionr :	/
E-File nr. :		First registration :	01/04/2015
VFS-nr. :		Color :	WHITE
Make + Model :	VOLVO / XC60	Fuel type :	
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	139g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1964
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	No
Animals transported:	Yes	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:			Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	0-1.6 /	Rim :	/	Hubcap :
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	0-1.6 /	Rim :	/
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	235	65	R	17	H
Rear tyre	235	65	R	17	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE		MEERDERE	
		Repair paint - LI	New paint - E	Depr.	Total	
4	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	
[x]	REAR LIGHT/RIGHT		HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total	
8	0 LU =0.00 EUR	0 EUR		50 %		
		Repair paint - LI	New paint - E	Depr.	Total	
8	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR	
[x]	REAR MUDGUARD/LEFT/REAR		HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total	
5	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR	
[x]	BONNET/LEFT/CENTER		DENT			
	Number	Code	Description	Unit price	Depr.	Total
0	0					
[x]	BONNET/CENTER/LEFT/FRONT		DENT			
		Repair paint - LI	New paint - E	Depr.	Total	
2	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR	
[x]	LIGHTS/RIGHT/FRONT		OTHER DAMAGES		DAGLICHT	
		Repair paint - LI	New paint - E	Depr.	Total	
3	0 LU =0.00 EUR	0 EUR		50 %		
		Repair paint - LI	New paint - E	Depr.	Total	
3	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR	
[x]	FRONT BUMPER/RIGHT/CORNER		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
1	0 LU =0.00 EUR	0 EUR		50 %		
		Repair paint - LI	New paint - E	Depr.	Total	
1	20 LU =96.00 EUR	0 EUR	235.80 EUR	50 %	331.80 EUR	

Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE BROKEN / CRACKED

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR	0 EUR		50 %	
	Repair paint - LI	New paint - E	Depr.	Total
6 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
7	I 6	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	87.48 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FRONT BUMPER	403.20 EUR	50 %	403.20 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	DAGLICHT	50.00 EUR	50 %	50.00 EUR
Number	Code	Description	Unit price	Depr.	Total
6	1	MIRROR COVER	120.00 EUR	50 %	120.00 EUR
Number	Code	Description	Unit price	Depr.	Total
8	1	REAR LIGHT	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
735.00	290.08	74.00	211.80	308.20	144.00	87.48	114.00	0	0
367.50	145.04	37.00	105.90	154.10	72.00	87.48	57.00	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
87.48	1877.08	0	1964.56
HOG: 0	BG: 0		NA Deprec. 1026.02
			0.00%
			TOTAL 1026.02

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/04/2017 Hour : 08:02 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	