

ATRNTD

☒ EFFECTIVE ☐ NOT EXECUTED ☐ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	145905 KM
File nr. :	1388017	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DCY083 / YV1MW84F1C2695823 /		yr of constructionr :	/
E-File nr. :		First registration :	12/04/2012
VFS-nr. :		Color :	GREY
Make + Model :	VOLVO / V50	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KBC GROEP NV	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	V50 BRE DRIVe Start/Stop 99g 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :	OK	[x]	Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	1.6-2 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :			/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	1.6-2 /	Rim :		/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :			/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT			SCRATCH WITH PAINT DAMAGE		MEERDERE	
			Repair paint - LI	New paint - E		Depr.	Total
2	0	LU =0.00 EUR		211.80 EUR		50 %	211.80 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT			DENT			
	Number	Code	Description	Unit price	Depr.	Total	
3	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR	
[x]	REAR DOOR/RIGHT/FRONT			DENT			
	Number	Code	Description	Unit price	Depr.	Total	
4	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR	
[x]	FRONT MUDGUARD/RIGHT/FRONT			SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E		Depr.	Total
1	0	LU =0.00 EUR		220.18 EUR		50 %	220.18 EUR
[x]	FRONT BUMPER/RIGHT/SIDE			SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E		Depr.	Total
1	0	LU =0.00 EUR		211.80 EUR		50 %	211.80 EUR

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
431.98	211.80	115.56	115.56	95.00	0	0	0	0	0
215.99	105.90	115.56	115.56	95.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
326.12	643.78	0	969.90
HOG: 0	BG: 0		NA Deprec. 648.01
			0.00%
			TOTAL 648.01

APPRAISAL

www.vabfleetservices.be

Date : 11/04/2017

4/4

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min	Towing time : 0 min
	Reason :	Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 11/04/2017 Hour : 10:55	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	