

AR58BS

☒ EFFECTIVE    ☐ NOT EXECUTED    ☒ COLLECTION    ☐ DELIVERY

[x] = Status Modification

|                               |                                      |                          |                               |
|-------------------------------|--------------------------------------|--------------------------|-------------------------------|
| Commissionar :                | KBC REMARKETING                      | Cleanliness :            | INT: DIRTY [x] EXT: CLEAN [x] |
| Owner :                       |                                      | Mileage :                | 206528 KM                     |
| File nr. :                    | 1386073                              | Mileage start / arrival: | 0 / 0                         |
| Reg number / Chassis / Ref :  |                                      | Mileag ref. service :    | 0                             |
| 1FRZ976 / WVGZZZ1TZEW025360 / |                                      | yr of constructionr :    | /                             |
| E-File nr. :                  |                                      | First registration :     | 07/10/2013                    |
| VFS-nr. :                     |                                      | Color :                  | BLUE                          |
| Make + Model :                | VOLKSWAGEN / TOURAN                  | Fuel type :              | DIESEL                        |
| Object nr. :                  | 61232                                | Fuel :                   |                               |
| Classification :              |                                      | Environment Class:       | EURO 5                        |
| Customer company :            | ELSTER NV/ESSEN                      | Co2:                     | 121g/km                       |
| Driver :                      |                                      | Remote controls:         | 2                             |
| Covering :                    | TISSUE                               | Number keys :            | 2 [x]                         |
| Vehicle kind :                | VEHICLE                              | Seats (minivan) :        | 5 [x]                         |
| Vehicle type :                | TOURAN Highline BMT Start/Stop 105PK | Country registration :   | BELGIUM                       |

|                              |            |                     |         |
|------------------------------|------------|---------------------|---------|
| VAT over the margin - car:   | No         | Metallic paint:     | Yes     |
| Variant car:                 | MONOVOLUME | Engine size:        | 1598    |
| Gear box :                   | Manueel    | Number of places:   | 5       |
| Number of gears:             | 6          | Number of doors:    | 5       |
| HP:                          | 105        | kW:                 | 77      |
| Fisc HP                      |            | Imported vehicle:   |         |
| Animals transported:         |            | Smoked in vehicle:  |         |
| Due date vehicle inspection: |            | Extra set of tires: | No      |
|                              |            | Use:                | Unknown |
| General condition:           |            |                     |         |

|                              |     |                         |                       |     |
|------------------------------|-----|-------------------------|-----------------------|-----|
| Original registr. number :   | OK  | Service manual :        | OK                    | [x] |
| Cert. of reg. / Part 1:      | OK  | [x]                     | Cert. of conformity : | OK  |
| Cert. of reg. copy / Part 2: |     | Insurance certificate : |                       |     |
| Warning vest :               |     | Transport licence :     |                       |     |
| Tax certificate :            |     | Navigation CD/SD/DVD    |                       |     |
| Fuel card :                  |     | Car radio :             | OK                    | [x] |
| Mobile phone kit :           |     | Extinguisher :          | OK                    | [x] |
|                              |     | Warning triangle :      | OK                    | [x] |
| First aid kit :              |     | Oil level :             | OK                    | [x] |
| Jack, wheelspanner :         | [x] | Filled up :             | 0                     |     |

## Wheels and tyres: Winter tires

|            |     |          |        |     |     |       |       |       |   |          |          |  |
|------------|-----|----------|--------|-----|-----|-------|-------|-------|---|----------|----------|--|
| Wheel FL:  | [x] | KLÉBER   | Tyre : | OK  | [x] | 2-4 / | Rim : |       | / | Hubcap : |          |  |
| Wheel RL : | [x] | GOODYEAR | Tyre : | OK  | [x] | 4-6 / | Rim : |       | / | Hubcap : |          |  |
| Wheel FR : | [x] | KLÉBER   | Tyre : | [x] | OK  | [x]   | 2-4 / | Rim : |   | /        | Hubcap : |  |
| Wheel RR : | [x] | GOODYEAR | Tyre : | OK  | [x] | 4-6 / | Rim : |       | / | Hubcap : |          |  |
| Wheel RES: | [x] |          | Tyre : | OK  |     | /     | Rim : |       | / | Hubcap : |          |  |

| [x]        | Width | Height | Type | Rim | Index    |
|------------|-------|--------|------|-----|----------|
| Front tyre | 205   | 55     | R    | 16  | WINTER H |
| Rear tyre  | 205   | 55     | R    | 16  | WINTER H |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |  |   |          |  |
|------------|--|--------|----|---|-------|--|---|----------|--|
| Wheel FL:  |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |  |
| Wheel RL : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |  |
| Wheel FR : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |  |
| Wheel RR : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |  |
| Wheel RES: |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |  |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

|     |                         |                           |        |
|-----|-------------------------|---------------------------|--------|
| [x] | REAR BUMPER/CENTER/LEFT | SCRATCH WITH PAINT DAMAGE |        |
| [x] | FRONT DOOR/LEFT/REAR    | DENT                      | + KRAS |
| [x] | FRONT DOOR/RIGHT/REAR   | SCRATCH WITH PAINT DAMAGE |        |

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

|     |                          |                   |               |            |
|-----|--------------------------|-------------------|---------------|------------|
| [x] | REAR MUDGUARD/LEFT/FRONT | DENT              |               |            |
|     |                          | Repair paint - LI | New paint - E | Depr.      |
| 4   | 0 LU =0.00 EUR           | 308.20 EUR        |               | 50 %       |
|     |                          |                   |               | 308.20 EUR |
| [x] | REAR WINDOW/LEFT         | WINDOW DAMAGE     |               |            |
|     |                          | Repair paint - LI | New paint - E | Depr.      |
| 5   | 25 LU =120.00 EUR        | 0 EUR             |               | 50 %       |
|     |                          |                   |               | 120.00 EUR |
| [x] | WINDSCREEN/BELOW/LEFT    | WINDOW DAMAGE     |               |            |
|     |                          | Repair paint - LI | New paint - E | Depr.      |
| 3   | 25 LU =120.00 EUR        | 0 EUR             |               | 50 %       |
|     |                          |                   |               | 120.00 EUR |
| [x] | BONNET/CENTER/RIGHT      | DENT              |               |            |
|     |                          | Repair paint - LI | New paint - E | Depr.      |
| 2   | 0 LU =0.00 EUR           | 290.08 EUR        |               | 50 %       |
|     |                          |                   |               | 290.08 EUR |

### Accessories and others

|     |                              |                   |               |       |
|-----|------------------------------|-------------------|---------------|-------|
| [x] | OUTSIDE MIRROR LEFTHAND SIDE | BROKEN / CRACKED  |               |       |
|     |                              | Repair paint - LI | New paint - E | Depr. |
| 6   | 0 LU =0.00 EUR               | 0 EUR             |               | 50 %  |

### Others

CLEANLINESS INTERIOR

| Number | Code | Description                          | Unit price        | Depr.      | Total      |
|--------|------|--------------------------------------|-------------------|------------|------------|
| 1      | I 5  | specifiek-per-kwartier-a-vab-rein-03 | CLEANING INTERIOR | 14.58 EUR  | 72.90 EUR  |
| Number | Code | Description                          | Unit price        | Depr.      | Total      |
| 1      | I 1  | i-vab-geur-01                        | ODOUR TREATMENT   | 152.58 EUR | 152.58 EUR |

## Pieces

|   | Number | Code | Description  | Unit price | Depr. | Total      |
|---|--------|------|--------------|------------|-------|------------|
| 3 | 1      |      | WIND SCREEN  | 367.20 EUR | 50 %  | 367.20 EUR |
|   | Number | Code | Description  | Unit price | Depr. | Total      |
| 6 | 1      |      | MIRROR COVER | 120.00 EUR | 50 %  | 120.00 EUR |
|   | Number | Code | Description  | Unit price | Depr. | Total      |
| 5 | 1      |      | BACK WINDOW  | 250.00 EUR | 50 %  | 250.00 EUR |

| 1      | 2      | 3      | 4      | 5      | 6      | 7 | 8 | 9 | 10 |
|--------|--------|--------|--------|--------|--------|---|---|---|----|
| 225.48 | 290.08 | 487.20 | 308.20 | 370.00 | 120.00 | 0 | 0 | 0 | 0  |
| 225.48 | 145.04 | 243.60 | 154.10 | 185.00 | 60.00  | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                    |
|------------|-------------|---------|--------------------|
| 225.48     | 1575.48     | 0       | 1800.96            |
| HOG: 0     | BG: 0       |         | NA Deprec. 1013.22 |
|            |             |         | 0.00%              |
|            |             |         | TOTAL 1013.22      |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

|                               |                                  |                                 |
|-------------------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min            | Waiting time : 0 min<br>Reason : | Towing time : 0 min<br>Reason : |
| NOT EXECUTED : No<br>Reason : |                                  |                                 |
| Remark :                      |                                  |                                 |

## Prices in EUR without VAT

|                                                                                                                                                                      |                                |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|
| Authorized by customer :<br><br>Remark authorized customer :<br><br>Date : 10/04/2017      Hour : 13:48<br>Company :<br>Executed by VAB Fleet Services<br>E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br>                                              |                                |