

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	80565 KM
File nr. :	1388174	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CGG873 / WMWSW11040T178520 /		yr of constructionr :	2011 / 00
E-File nr. :		First registration :	18/11/2011
VFS-nr. :		Color :	BLACK
Make + Model :	MINI / ONE	Fuel type :	DIESEL
Object nr. :	39201	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	AMSIT SA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	MINI One 90PK DPF	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	4
Number of gears:	6	Number of doors:	3
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	Yes
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RL : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RR : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	175	65	R	15	M+S
Rear tyre	175	65	R	15	M+S

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/CENTER DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR	169.44 EUR		50 %	169.44 EUR

[x] REAR DOOR/CENTER/LEFT DENT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] REAR MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE +DEUKEN

	Repair paint - LI	New paint - E	Depr.	Total
7 0 LU =0.00 EUR	246.56 EUR		50 %	246.56 EUR

[x] ROOF/CENTER/RIGHT OTHER DAMAGES HAGEL + KRAS DOOR LAK

Number	Code	Description	Unit price	Depr.	Total
0	0				

[x] FRONT DOOR/LEFT/FRONT SCRATCH WITH PAINT DAMAGE + DEUKEN

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR	254.68 EUR		50 %	254.68 EUR

[x] FRONT DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE + DEUKEN

	Repair paint - LI	New paint - E	Depr.	Total
8 0 LU =0.00 EUR	254.68 EUR		50 %	254.68 EUR

[x] BONNET/CENTER/RIGHT OTHER DAMAGES HAGEL

Number	Code	Description	Unit price	Depr.	Total
0	0				

[x] FRONT BUMPER/CENTER/LEFT HOLE/CRACK/TORN

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	0 EUR		50 %	
	Repair paint - LI	New paint - E	Depr.	Total
3 20 LU =96.00 EUR	0 EUR	188.64 EUR	50 %	284.64 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 3 i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		43.74 EUR

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	FRONT BUMPER	322.56 EUR	50 %	322.56 EUR

1	2	3	4	5	6	7	8	9	10
328.74	0	607.20	63.00	254.68	169.44	246.56	254.68	0	0
328.74	0	303.60	63.00	127.34	84.72	123.28	127.34	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
391.74	1532.56	0	1924.30
HOG: 0	BG: 1		NA Deprec. 1158.02
			0.00%
			TOTAL 1158.02

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/04/2017 Hour : 11:44 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	