

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	39209 KM
File nr. :	1388374	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EWE892 / VF15RJL0H48758656 /		yr of constructionr :	/
E-File nr. :		First registration :	05/04/2013
VFS-nr. :		Color :	SILVER
Make + Model :	RENAULT / CLIO	Fuel type :	DIESEL
Object nr. :	49284	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	RANDSTAD GROUP BELGIUM NV	Co2:	83g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	0
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	CLIO IV BER e-Expression St&St 90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x] OK [x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	185	65	R	15	H
Rear tyre	185	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT DOOR/LEFT/REAR

SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Interior

[x] SEAT REAR L

STAIN

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

Others

HUB CAP FL

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

HUB CAP REAR L

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

1	2	3	4	5	6	7	8	9	10
14.58	96.00	0	0	0	0	0	0	0	0
14.58	48.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
14.58	96.00	0	110.58
HOG: 0	BG: 1		NA Deprec. 62.58
			0.00%
			TOTAL 62.58

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/04/2017 Hour : 13:00 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	