

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 93623 KM |
| File nr. : | 1416911 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1FH0785 / WAUZZZ8V0EA012147 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 01/07/2013 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | AUDI / A3 SPORTBACK | Fuel type : | DIESEL |
| Object nr. : | 75648 | Fuel : | |
| Classification : | E | Environment Class: | EURO 5 |
| Customer company : | CLOSE RANGE CONSULTING | Co2: | 99g/km |
| Driver : | | Remote controls: | 1 |
| Covering : | LEATHER | Number keys : | 1 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | | Metallic paint: | Yes |
| Variant car: | | Engine size: | 1598 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 105 | kW: | 77 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | |
| | | Use: | Unknown |
| General condition: | | | |

| | |
|-------------------------------------|---------------------------|
| Original registr. number : OK | Service manual : OK [x] |
| Cert. of reg. / Part 1: | Cert. of conformity : OK |
| Cert. of reg. copy / Part 2: OK [x] | Insurance certificate : |
| Warning vest : | Transport licence : |
| Tax certificate : | Navigation CD/SD/DVD |
| Fuel card : | Car radio : OK [x] |
| Mobile phone kit : | Extinguisher : OK [x] |
| First aid kit : OK [x] | Warning triangle : OK [x] |
| Jack, wheelspanner : | Oil level : OK [x] |
| | Filled up : 0 |

Wheels and tyres: Summer tires

| |
|---|
| Wheel FL: [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RL : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap : |
| Wheel FR : [x] CONTINENTAL Tyre : [x] OK [x] 2-4/ Rim : / Hubcap : |
| Wheel RR : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap : |
| Wheel RES: [x] Tyre : OK / Rim : / Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225 | 45 | R | 17 | Y |
| Rear tyre | 225 | 45 | R | 17 | Y |

Remark :

Wheels and tyres:

| |
|---|
| Wheel FL: Tyre : OK / Rim : / Hubcap : |
| Wheel RL : Tyre : OK / Rim : / Hubcap : |
| Wheel FR : Tyre : OK / Rim : / Hubcap : |
| Wheel RR : Tyre : OK / Rim : / Hubcap : |
| Wheel RES: Tyre : OK / Rim : / Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE
- [x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE
- [x] BONNET/CENTER/LEFT/FRONT CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] FRONT BUMPER/LEFT/CORNER SCRATCH WITH PAINT DAMAGE

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|------------|------------|
| 1 | I 1 | i-vab-sp-01 | SPOTREPAIR | 115.56 EUR | 115.56 EUR |

Others

RIM FRONT LEFT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 2 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|-------|---|---|---|---|---|---|---|----|
| 115.56 | 95.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 115.56 | 95.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 210.56 | 0 | 0 | 210.56 |
| HOG: 0 | BG: 1 | | NA Deprec. 210.56 |
| | | | 0.00% |
| | | | TOTAL 210.56 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

| | | |
|---|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 07/07/2017 Hour : 09:34 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |